Yellow River

co-0807-008

Severity Score 5.25

Common: 9mi NW of Florala

<u>Drainage</u>: Blackwater Bay <u>GPS</u>: 31.095519537, -86.435215265 <u>Land owner</u>: RB: Unknown/ LB: James & Mary Phillips

<u>County</u>: <u>PLSS(T-R-S)</u>:

Covington 2N-16E-34 <u>State</u>:

Alabama

Parcel No.: RB: ? / LB: 13/49AC





Risk Factor	Ranking	Score
Channel Stability	Fair	1
Channel Alteration	None	0
Bank Erosion	Active	1
ВЕНІ	Moderate	0.5
Local NPSP	Obvious Sources	1
Shoring Structures	Present	1.5
Pipe Discharge	Not Present	0
Water Odors	Not Present	0
Fish Passage Barrier	Not Present	0
RB: Riparian Buffer	100+ ft	0
LB: Riparian Buffer	100+ ft	0
RB: Floodplain Access	Full	0
LB: Floodplain Access	Partial	0.25
	River Threat Index:	5.25

Feature	Within Range	Descriptive Field	
303(d)	Yes	METALS (MERCURY)	
Wetland Species	No	N/A	
Rare and Imperiled	No	N/A	
Sturgeon Spawning	No	N/A	
Candidate Mussels	Yes	FUZZY PIGTOE, SOUTHERN SANDSHELL	
Sturgeon C.H.	No	N/A	

Notes: Shoring structure under Hwy 55 bridge composed of concrete and rip rap.

Additional Site Features

Infrequent None Stream Channel Woody Material: Impoundments: Substrate Composition: Medium Sand Sand Bank Material:

Restoration Recommendations: TBD