## Unnamed tributary

co-0820-r-008

Tram Rd

Sedimentation Risk Index

40

6.5mi N of Florala Common:

Clear Creek <u>GPS:</u> 31.099232101, -86.330790688 Rayonier Forest Resources LP DS, W&G Martin Heirs-<u>Drainage</u>: Land owner:

County: Covington  $\overline{PLSS}$  (T-R-S): 2N-17E-34 Parcel No.: 3;1

Road Name:

Alabama





Crossing Structure: US

Risk Factor	Ranking	Score
US Channel Morph	WETLAND	5
DS Channel Morph	DA	3
DS Bank Alteration	HIGH	1
Upstream Skew Angle	<5°	5
Crossing fill condition	Poor/Bare soil	1
Inlet/Outlet Condition	Sed Islands/Scouring	3
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	<21 y <sup>3</sup>	5
Approach Slope Mean	<2%	5
Soil K Factor	< 0.20	5
Upstream Rt Outlet	Bare soil	0
Upstream Lt Outlet	Bare soil	0
Upstream Rt Ditch	Bare soil	0
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Vegetated	1
Downstream Lt Outlet	Vegetated	1
Downstream Rt Ditch	Bare soil	0
Downstream Lt Ditch	Bare soil	0
Outlet Total	Partially Improved Outlet System	3
Ditches Total	Unimproved Drainage System	1
SRI Total	Medium Risk	40



Additional Site Features
Crossing Type and Quan

<u>Frossing Type and Quantity</u>: Culvert, 1 Metal **Crossing Materials**:

BoB, DmB, FoA,FuB,MBA,RaA

Soil Types: Rt Approach Prism Fill: 0.1 inLt Approach Prism Fill: 0.75in

Feature	Within Range	Descriptive Field	
303(d)	No	N/A	
Wetland Species	No	N/A	
Rare and Imperiled	No	N/A	
Land Use/ Cover	Yes	N/A/ EAST GULF COASTAL PLAIN INTERIOR UPLAND LONGLEAF PINE WOODLAND-LOBLOLLY MODIFIER	
Candidate Mussels	No	N/A	
Sturgeon C.H.	No	N/A	

Notes: Evidence of past aggregate on the road?