Unnamed tributary

wa-1105-004

Severity Score

Common:7.6mi SE of Laurel Hill, Long Rd bridge crossingDrainage:Pine Log CreekGPS: 30.890084885, -86.364442063Land owner:Ronald Hurst- DS/ Jasper Dickenson, US

County: PLSS(T-R-S): Parcel No.:

Walton 5N-21W-32 5.001/4.001 State: Florida





Risk Factor	Ranking	Score
Channel Stability	Excellent	0
Channel Alteration	In Recovery	1
Bank Erosion	None	0
BEHI	Non Eroding	0
Local NPSP	Moderate Potential	1
Shoring Structures	Present	1.5
Pipe Discharge	Not Present	0
Water Odors	Present	1.5
Fish Passage Barrier	Present	1.5
RB: Riparian Buffer	50-99 ft	0.5
LB: Riparian Buffer	50-99 ft	0.5
RB: Floodplain Access	None	0
LB: Floodplain Access	None	0
	River Threat Index:	7.5

Feature	Within Range	Descriptive Field	
303(d)	No	N/A	
Wetland Species	Yes	1-3 FOCAL SPECIES IN WETLAND AREAS	
Rare and Imperiled	No	N/A	
Land Use/ Cover	Yes	AGRICULTURAL/ WETLAND FORESTED MIX	
Candidate Mussels	No	N/A	
Sturgeon C.H.	No	N/A	

Additional Site Features Stream Channel Woody Material: Infrequent

Impoundments: Substrate Composition: Bank Material:

Rip Rap Medium Sand Sand

Notes: Rip rap and box culvert outfall drop blocking flow and fish passage. Sediment islands DS. Channel wide and shallow, as opposed to US narrow.