Titi Creek

ok-1022-001

Severity Score

4

Common: 7.7mi SE of Crestview

<u>Drainage</u>: Shoal River <u>Land owner</u>: USA- Eglin AFB <u>GPS</u>: 30.698776532, -86.462921107

<u>County</u>: <u>PLSS(T-R-S)</u>: <u>Parcel No.</u>: Okaloosa 2N-22W-1 State: Florida





Risk Factor	Ranking	Score
Channel Stability	Fair	1
Channel Alteration	None	0
Bank Erosion	Active	1
BEHI	Moderate	0.5
Local NPSP	No Evidence	0
Shoring Structures	Not Present	0
Pipe Discharge	Not Present	0
Water Odors	Not Present	0
Fish Passage Barrier	Not Present	0
RB: Riparian Buffer	0-29 ft	0.75
LB: Riparian Buffer	100+ ft	0
RB: Floodplain Access	None	0.75
LB: Floodplain Access	Full	0
	River Threat Index:	4

Feature	Within Range	Descriptive Field	
303(d)	No	N/A	
Wetland Species	No	N/A	
Rare and Imperiled	No	N/A	
Land Use/ Cover	Yes	INSTITUTIONAL/ STREAMS AND WATERWAYS	
Candidate Mussels	No	N/A	
Sturgeon C.H.	No	N/A	
		aterial: Numerous Woody Material Jams Coarse Sand	
B. 1.14 1		Course Sund	

Coarse Sand

Notes: Uncommon feature for Titi Creek. 270ft reach

452

Bank Material: