## Unnamed tributary

co-0820-r-003

Sedimentation Risk Index

Alabama

28

State:

4.4mi N of Florala Common:

Dry Creek <u>GPS:</u> 31.067773851, -86.339962557 Rayonier Forest Resources LP Drainage:
Land owner:

County: PLSS (T-R-S): Covington 1N-17E-10

<u>Parcel No.</u>:

Road Name:







**Crossing Structure: US** 

Risk Factor	Ranking	Score
US Channel Morph	DA	3
DS Channel Morph	WETLAND	5
DS Bank Alteration	HIGH	1
Upstream Skew Angle	5-30°	3
Crossing fill condition	Poor/Bare soil	1
Inlet/Outlet Condition	Blocked	1
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	>40 y <sup>3</sup>	1
Approach Slope Mean	<2%	5
Soil K Factor	0.21-0.40	3
Upstream Rt Outlet	Bare soil	0
Upstream Lt Outlet	Bare soil	0
Upstream Rt Ditch	Bare soil	0
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Bare soil	0
Downstream Lt Outlet	Bare soil	0
Downstream Rt Ditch	Bare soil	0



**Descriptive Field** 

Within

Range

Downstream Lt Outlet	Bare soil	0	303(d)	No	N/A
Downstream Rt Ditch	Bare soil	0	***		27/4
Downstream Lt Ditch	Bare soil	0	Wetland Species	No	N/A
Outlet Total	Unimproved Outlet System	1	Species		
Ditches Total	Unimproved Drainage System	1	Rare and	No	N/A
SRI Total	High Risk	28	Imperiled		
Additional Site Features			Land Use/ Cover	Yes	N/A/ EAST GULF COASTAL PLAIN INTERIOR UPLAND LONGLEAF PINE
Crossing Type and Quantity	: Culvert, 1				WOODLAND-LOBLOLLY MODIFIER
Crossing Materials:	Metal		Candidate	No	N/A
Soil Types:	<i>ypes</i> : BoB,BoC,CdC,DmB,EsC,FoA		Mussels		
Rt Approach Prism Fill:	1.5in		Sturgeon	No	N/A
Lt Approach Prism Fill:	2.0in		C.H.		

Feature

Notes: US channelized