Unnamed tributary

co-0831-r-007

Sedimentation Risk Index

Common: Drainage: Land owner: 6.1mi SW of Opp Mulberry Creek Elma Sasser LE

GPS: 31.208589, -86.311083

County: Covington 3N-17E-24 15 \overline{PLSS} (T-R-S):

Parcel No.:

Road Name: Tweedle Bell Rd







Crossing Structure: DS

Risk Factor	Ranking	Score
US Channel Morph	PONDED	1
DS Channel Morph	E	5
DS Bank Alteration	HIGH	1
Upstream Skew Angle	>30°	1
Crossing fill condition	Good/Vegetated	5
Inlet/Outlet Condition	No Impairment	5
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	<21 y ³	5
Approach Slope Mean	<2%	5
Soil K Factor	< 0.20	5
Upstream Rt Outlet	Vegetated	1
Upstream Lt Outlet	Rip Rap	1
Upstream Rt Ditch	Bare soil	0
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Vegetated	1
Downstream Lt Outlet	Vegetated	1
Downstream Rt Ditch	Bare soil	0
Downstream Lt Ditch	Bare soil	0
Outlet Total	Improved Outlet System	5
Ditches Total	Unimproved Drainage System	1
SRI Total	Medium Risk	42

		Covington
		(Malong Walton
		, 400 0
<u> </u>	SHAD WANTED	Google

Feature	Within Range	Descriptive Field	
303(d)	No	N/A	
Wetland Species	No	N/A	
Rare and Imperiled	No	N/A	
Land Use/ Cover	Yes	N/A/ DEVELOPED OPEN SPACE	
Candidate Mussels	No	N/A	
Sturgeon C.H.	No	N/A	

Additional Site Features

Crossing Type and Quantity: Culvert, 1 PVC Crossing Materials:

CdC,DmB,FoA,FuB,MBA

Soil Types: Rt Approach Prism Fill: 0.25in Lt Approach Prism Fill: 0.1in

Notes: None