Unnamed tributary

co-0820-r-006

Sedimentation Risk Index

Alabama

38

State:

<u>Common</u>: 5.9mi N of Florala

Clear Creek GPS: 31.090768061, -86.336509468 <u>Drainage</u>:

Land owner: Rayonier Forest Resources LP County: PLSS (T-R-S): Covington 2N-17E-34 3

Parcel No.: Road Name: Tram Rd





Crossing Structure: US

Risk Factor	Ranking	Score
US Channel Morph	WETLAND	5
DS Channel Morph	DA	3
DS Bank Alteration	HIGH	1
Upstream Skew Angle	5-30°	3
Crossing fill condition	Poor/Bare soil	1
Inlet/Outlet Condition	Sed Islands/Scouring	3
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	<21 y ³	5
Approach Slope Mean	<2%	5
Soil K Factor	< 0.20	5
Upstream Rt Outlet	Vegetated	1
Upstream Lt Outlet	Bare soil	0
Upstream Rt Ditch	Bare soil	0
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Vegetated	1
Downstream Lt Outlet	Vegetated	1
Downstream Rt Ditch	Bare soil	0
Downstream Lt Ditch	Bare soil	0
Outlet Total	Partially Improved Outlet System	3
Ditches Total	Unimproved Drainage System	1
SRI Total	Medium Risk	38

Culvert, 1 PVC

1.0in

0.25in

FoA,FuB,LuB,MBA

Compan	
(Salodo)	
s recognic Supple Strategies Strategies Strategies	

Feature	Within Range	Descriptive Field	
303(d)	No	N/A	
Wetland Species	No	N/A	
Rare and Imperiled	No	N/A	
Land Use/ Cover	No	N/A	
Candidate Mussels	No	N/A	
Sturgeon C.H.	No	N/A	

Notes: None.

Additional Site Features Crossing Type and Quantity: Crossing Materials:

Soil Types: Rt Approach Prism Fill:

Lt Approach Prism Fill: