Unnamed tributary

wa-0716-r-004

Sedimentation Risk Index

36

Florida

State:

3.8mi NE of Mossy Head Common:

<u>GPS:</u> 30.758112, -86.252781 Shoal River <u>Drainage</u>: Helen Bright-US, Josh Graber & Kevin Millner-DS Land owner:

County: Walton $\overline{PLSS(T-R-S)}$:

Parcel No.: Road Name: 3N-20-16-28060 9.0150; 25.0220 Trout Rd





Crossing Structure: DS

Risk Factor	Ranking	Score
US Channel Morph	WETLAND	5
DS Channel Morph	DA	3
DS Bank Alteration	HIGH	1
Upstream Skew Angle	5-30°	3
Crossing fill condition	Poor/Bare soil	1
Inlet/Outlet Condition	Sed Islands/Scouring	3
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	<21 y ³	5
Approach Slope Mean	<2%	5
Soil K Factor	< 0.20	5
Upstream Rt Outlet	Bare soil	0
Upstream Lt Outlet	Bare soil	0
Upstream Rt Ditch	Bare soil	0
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Other	0
Downstream Lt Outlet	Other	0
Downstream Rt Ditch	Bare soil	0
Downstream Lt Ditch	Bare soil	0
Outlet Total	Unimproved Outlet System	1
Ditches Total	Unimproved Drainage System	1

High Risk

Goode			
Feature	Within Range	Descriptive Field	
303(d)	No	N/A	
Wetland Species	Yes	1-3 FOCAL SPECIES IN UPLAND AREAS	
Rare and Imperiled	Yes	SPECKLED CHUB, IRONCOLOR SHINER, GOLDSTRIPE DARTER	
Land Use/ Cover	Yes	N/A/ MDC-INACTIVE LAND WITH STREET PATTERNS BUT WITHOUT STRUCTURES	
Candidate	No	N/A	

N/A

SRI Total **Additional Site Features**

Culvert, 1 Crossing Type and Quantity: Crossing Materials: Metal 8,17,17,32 Soil Types: Rt Approach Prism Fill: 0.5in Lt Approach Prism Fill: 0.5in

Notes: BMPs DS outlets

36

Mussels

Sturgeon C.H.