

Measurments 1-5 with concentration Measurments 6-10 angle only

 mean angle
 5

 st dev
 5

 mean angle
 10

 st dev
 10

 5
 21,68

 5
 1,02

 10
 22,02

 10
 0,58