

Maintenance Inspection Report


Property: 123 Test Street, Unit 4B, Toronto ON

Inspector: Mike Chen, Building Superintendent

Date of Inspection: February 12, 2026

During the scheduled maintenance inspection, the following issues were identified in the tenant's unit:

1. Water stain on kitchen ceiling (approx. 18 inches diameter)
2. Window latch broken in bedroom — unit not secure
3. Bathroom exhaust fan inoperative



Recommended action: Repair ceiling leak from unit above (5B), replace window latch hardware, service exhaust fan motor.