

Certificate of Release to Service

NL66-2026-0011

Independent certifying staff — ML.A.801(b)(2)

AIRCRAFT

REGISTRATION	MANUFACTURER AND TYPE	SERIAL NUMBER	HOURS / LAUNCHES
PH-9876	Schempp-Hirth Duo Discus	512	1284 h / 2611

MAINTENANCE CARRIED OUT

Winter inspection and rectification following hangar rash and a heavy landing. Right wing shell delamination repaired at the outboard aileron hinge. Aileron removed, repaired, refinished and rebalanced. Complete control system disconnected, inspected, reassembled and rigged; independent inspection of all control connections carried out and recorded. Main undercarriage leg removed, crack tested and refitted with new bushes. Gear doors realigned. Wheel brake overhauled and bled. Canopy frame bonding repaired and locking mechanism adjusted. Pitot-static system leak checked. Instrument panel removed for access and refitted; all instruments functionally checked. Batteries load tested and one replaced. Transponder functionally checked and altitude encoder correlation verified. Complete refinish of upper wing surfaces including gel coat repair. Weighing carried out and a new weight and balance amendment prepared. All placards checked; three replaced.

WORK PERIOD

WORK STARTED	MAINTENANCE COMPLETED	DAYS WORKED	WORK ORDER
6 November 2025	27 February 2026	23	WO-2025-041

MAINTENANCE DATA USED

REFERENCE	REVISION	DATE
Duo Discus Maintenance Manual, chapter 2	Rev. 12	4 April 2023
Duo Discus Maintenance Manual, chapter 4	Rev. 12	4 April 2023
Duo Discus Maintenance Manual, chapter 6	Rev. 12	4 April 2023
Duo Discus Repair Manual	Rev. 5	18 September 2021
Schempp-Hirth TN 396-31	Issue 3	22 January 2024
Schempp-Hirth TN 396-34	Issue 1	9 May 2025
AD 2021-0044	—	12 February 2021
AD 2023-0187	—	3 August 2023
EASA AD 2024-0091	—	17 April 2024
Tost wheel brake overhaul instruction	Rev. 2	1 June 2019
Becker ATC 4401 installation manual	Rev. 4	30 November 2022
Hoffmann gel coat refinishing procedure	Rev. 1	14 March 2018
Club AMP, sailplane PH-9876	Issue 6	2 January 2026
EASA Part-ML Appendix I guidance	—	September 2025

PARTS AND MATERIALS INSTALLED

PART NUMBER	BATCH / SERIAL	RELEASE DOCUMENT
V2-1140-05	SN 41290	EASA Form 1 ref. 88213
Tost 3.00-4 brake shoe set	B-2291	EASA Form 1 ref. 88477
6005-2RS	B-90114	EASA Form 1 ref. 88478
Bush 12x16x20	B-90115	EASA Form 1 ref. 88478
Panasonic LC-R127R2PG	SN 7741902	EASA Form 1 ref. 89001
Canopy lock pin 4.0	B-11274	EASA Form 1 ref. 89114
Gel coat, white, 2.5 kg	Batch 2025-114	Conformity cert. 2025-114
Epoxy laminating resin L285	Batch 4471	Conformity cert. 4471
Hardener 285	Batch 4471	Conformity cert. 4471
Glass fabric 92110	Batch 8871	Conformity cert. 8871

LIMITATIONS TO AIRWORTHINESS OR OPERATIONS

Maintenance could not be completed in full. The following items remain outstanding and are deferred: (1) the transponder altitude encoder is due for recalibration within 30 days; (2) the right wing tip wheel bearing is worn but within limits and is to be replaced at the next inspection. The aircraft is released to service subject to these limitations. Operation under IFR is not permitted until item (1) is closed.

CERTIFICATION

F. Example, holder of aircraft maintenance licence NL.66.00000, certifies that the work specified, except as otherwise specified, was carried out in accordance with Part-ML, and in respect to that work, the aircraft is considered ready for release to service.

LICENCE NUMBER
NL.66.00000

DATE OF ISSUE
27 February 2026

SIGNATURE

Issued under ML.A.801(b)(2) of Regulation (EU) No 1321/2014, Annex Vb (Part-ML). Certification statement per AMC1 ML.A.801(e). Issued by a computer release-to-service system; the competent authority has been satisfied that only the person identified above may electronically issue this certificate.

PERSONNEL WHO CARRIED OUT THE WORK

Record purposes only — ML.A.801(d). Certification is by the signatory above.

NAME	LICENCE NUMBER	ROLE
J. de Vries	NL.66.11111	Assisted
M. Jansen	—	Independent inspection
P. Willemsen	NL.66.22222	Assisted
A. Bakker	—	Assisted
S. Groen	NL.66.33333	Independent inspection
H. Vermeulen	—	Assisted

PHOTOGRAPHIC RECORD, HELD SEPARATELY

FILE	SHA-256 (FIRST 16)	CAPTURED
c1a0-...-77b2.jpg	4a19c0ff2b7d8e01	8 November 2025 09:41
d2b1-...-18c3.jpg	b7710e4c9a2f3d55	8 November 2025 14:02
e3c2-...-29d4.jpg	2f0c8a91bd47e6a3	22 November 2025 11:15
f4d3-...-3ae5.jpg	91de20b7c4a80f16	6 December 2025 10:33
a5e4-...-4bf6.jpg	0c47a9e13f8b25dd	19 December 2025 15:57
b6f5-...-5c07.jpg	7e13cd88a04f9b62	10 January 2026 08:24
c706-...-6d18.jpg	38ba07f2c91e4d70	24 January 2026 13:46
d817-...-7e29.jpg	e502419dbc7a3f88	7 February 2026 09:09
e928-...-8f3a.jpg	5adc81093e2b7f14	21 February 2026 16:31
fa39-...-904b.jpg	c67b3e05a1d29f4e	27 February 2026 12:02

Photographs are bound to this certificate by the hashes listed above.