


O-ring failure in the Challenger



MORTON THROKOL, INC.
Wasatch Operations

* No Erosion

INFORMATION ON THIS PAGE WAS PREPARED TO SUPPORT AN ORAL PRESENTATION
AND CANNOT BE CONSIDERED COMPLETE WITHOUT THE ORAL DISCUSSION

O-ring failure in the Challenger

