



Oring failure in the Challenger

2

3










Rubber O-rings

prevent leaks from the fuel tank

<https://slideplayer.com/slide/17983085/>

O-ring failure in the Challenger




Rubber O-rings

prevent leaks from the fuel tank

<https://slideplayer.com/slide/17983085/>

O-ring failure in the Challenger



MORTON THROKOL, INC.
Wasatch Operations

* No Erosion

INFORMATION ON THIS PAGE WAS PREPARED TO SUPPORT AN ORAL PRESENTATION
AND CANNOT BE CONSIDERED COMPLETE WITHOUT THE ORAL DISCUSSION