

#	Valor referencial (Vr)	#	Valor medido (Vm)	#	Error absoluto (Ea)	%	Error relativo (Er)
	3,3		3,298		0,002		0,06060606061%
	3,3		3,299		0,001		0,0303030303%
	3,3		3,297		0,003		0,09090909091%
	3,3		3,298		0,002		0,06060606061%
	3,3		3,295		0,005		0,1515151515%
	3,3		3,296		0,004		0,1212121212%
	3,3		3,299		0,001		0,0303030303%
	3,3		3,297		0,003		0,09090909091%
	3,3		3,298		0,002		0,06060606061%
	3,3		3,299		0,001		0,0303030303%

#	Valor referencial (Vr)	#	Valor medido (Vm)	#	Error absoluto (Ea)	%	Error relativo (Er)
	5		5,000		0		0%
	5		5,002		0,002		0,04%
	5		5,001		0,001		0,02%
	5		5,000		0		0%
	5		4,999		0,001		0,02%
	5		5,001		0,001		0,02%
	5		5,000		0		0%
	5		5,001		0,001		0,02%
	5		5,000		0		0%
	5		5,001		0,001		0,02%

#	Valor referencial (Vr)	#	Valor medido (Vm)	#	Error absoluto (Ea)	%	Error relativo (Er)
	12		12,005		0,005		0,04166666667%
	12		12,002		0,002		0,01666666667%
	12		11,999		0,001		0,008333333333%
	12		12,004		0,004		0,03333333333%
	12		12,005		0,005		0,04166666667%
	12		12,006		0,006		0,05%
	12		12,004		0,004		0,03333333333%
	12		12,003		0,003		0,025%
	12		12,005		0,005		0,04166666667%
	12		12,002		0,002		0,01666666667%

RESISTENCIA EN SERIE

$$R_{eq} = R1 + R2$$


$$R_{eq} = 1000 + 220 = 1220 \Omega$$

$$\text{Valor referencial} = 1220$$



$$\text{Resistencia medida} = 1235 \Omega$$

$$\text{Error absoluto} = |Vr - Vm| = 1220 - 1235 = 0,35$$

$$\text{Error relativo} = (Ea / Vr) * 100 = (0,35 / 1220) * 100 = 0,029\%$$



Resistencias en serie



RESISTENCIA EN PARALELO

$$1/R_{eq} = 1/R1 + 1/R2$$


$$R_{eq} = 180 \Omega$$

$$\text{Valor referencial} = 180$$

$$\text{Resistencia medida} = 181,1 \Omega$$

$$\text{Error absoluto} = |Vr - Vm| = 180 - 181,1 = 1,1$$

$$\text{Error relativo} = (Ea / Vr) * 100 = (1,1 / 180) * 100 = 0,61\%$$



Resistencias en paralelo

