Stress connects a surface normal to a traction