## Sensor Cable Assembly Specifications

## Rain Gauge Sensor:

Device: Davis AeroCone 6464M

Connector: M12, 5 pos

Connector PN: T4111001051-000

Cable Length: 10m

Pinout:


Pin	Wire (Legacy)	Wire (Updated)
1	DNP	DNP
2	Red	Red
3	Green	Black
4	DNP	DNP
5	DNP	DNP


Note: Unpopulated wires are not needed, these should be trimmed back to point of jacket being stripped

## Appendix A: Installation of M12 Connector



Unshielded Cable





- Connector components install on cable
- 2. Cable jacket should be stripped as shown
- For 3-8-position, install wire to correct insert position (wire plug should be preferred to crimp on the wire)
- Turn the M2.5 screw with suitable tool, torque to 0.2Nm [1.77 in.-lb.]
  - For 12-position, sold the wire
- Install straight housing
- 6. Install seal, pinch ring, pressing screw
- 7. Pressing screw should be tightened with torque recommended as 1 Nm [8.85 in.-lb.]
- Cable outlet: PG7 (cable feed: 4-6mm) PG9 (cable feed: 6-8mm)

## Taken from:

https://www.te.com/commerce/DocumentDelivery/DDEController?Action=showdoc&DocId=Spec ification+Or+Standard%7F114-137144%7FA7%7Fpdf%7FEnglish%7FENG SS 114-137144 A 7.pdf%7FT4111001051-000