Daily Completion And Workover Report

Alcor #1 DATE: 11/11/2012

OPERATOR: Great Bear Petroleum Operating, LLC

FOREMAN: Pablo Headworth Report No.: 84 TMD:

ENGINEER: Dylan Garett SECTION: AFE#: 005 TVD: DSS: 84.0

FIELD: T7N - R14E - Sec 5 **TWP: AFE TMD/TWC:** 10,665.02 **FOOTAGE:**

COUNTY: North Slope RANGE: WI/NRI: Rig Name/No.:

STATE: ALASKA **KBELEV**: 209 ft **API**: 50-223-20026-00-00 **PBTD**:

QTY Workstring Component Description O.D.(in) I.D.(in) Length(ft)

Total BHA Length:

Page 1 of 1

PERFORATIONS DATA

STIMULATION DATA

Prop Conc:

Stage #: 1 Job Date: Contractor: Pumped Via:

Job Description: Gross Interval: Tracer:

Fluid Type: Pad Vol: Main Body Vol: Flush Vol: BLTR Oil/Other/M

Prop in Frm: Gas Type: Gas Vol:

Min Rate/psi: Max Rate/psi:

Min Rate/psi: Max Rate/psi: Ave Rate/psi:

ISIP: FSIP: 15 min. SI: Frac Grad. Initial/ Final: /

Accident: Env. Incident

Safety Meeting: Need to designate someone to bear watch. Walking surfaces, pinch points, pressure testing lines, Running Perforating Guns, Everyone has the right to

shut down job.

From	То	Hrs.	Activity Last 24 Hours		COST SUMMARY			
6:00	9:30	3.50	Waiting on crew from Dead horse,Call HES frac and Peak for	Class	Code	Description/Comments	Costs (\$)	
			9.8# at 06:30 am.	8770	104	Wellsite Supervision/update cost on well site supervisor 18	1,800.00	
9:30	14:00	4.50	Frac Equipment on location. Spot in equipment. Peak deliver 650 bbls 9.8# brine. Use Cement truck for Iron to use on job on location 11:30	8770	113	Equipment Rental/frac tree	1,050.00	
				8770	113	Equipment Rental/Haul water From Vern lake to Baroid	2,180.00	
			Continue to rig up to well.	8770	113	Equipment Rental/NC cat rental 1ea 115./day	115.00	
14:00	14:15	0.25	Before Job Safety meeting.	8770	113	Equipment Rental/Pickup Rental 140/day	140.00	
14:15	15:00	0.75	PTS choke good for 5000 psi. Disconnect PTS RU to HES CMT truck to Bled pressure to and Prime HT .400.	8770	201	Logging/Formation Eval/Testing/E-line 2 days 11-2 11-9	38,922.00	
15:00	15:15	0.25	Pressure test pump & lines to 6450 psi. Bled pressure off. Open	8770	201	Logging/Formation Eval/Testing/Flowback equipment,Pers	8,055.00	
			well on vacuum. took 4 bbls to fill well.	8770	208	Contingencies/.5%	2,613.00	
15:15	15:30	0.25	Start pumping @ 1.3BPM walk pressure up 3500 psi broke back to 2500 psi. Increase rate to 12 BPM @ 2800 psi 70 bbls away leak at HT shut down. Shut well in. Bled Pressure off.			Total Daily Cost:	54,875.00	
						Cumulative Cost to Date:	1,489,148.72	
15:30	17:00	1.50	Leak at single wing off HT-400. Lost union gasket. Change out.Install new Gasket. Clean up. Prime truck was having computor trouble on HT. E-TECT got computor running.					
17:00	17:25	0.42	Pressure test pump and lines to 6500 psi.					
17:25	19:00	1.58	Open well. Well head pressure 2399 psi.Come on line w/ HT. Pump not pumping smooth lost flow meter. Shut down. Pump 30 bbls. Drain lines and check flow meter. Impeller missing repair flow meter.					
19:00	19:30	0.50	Pressuure test pump lines 6500 psi. Bled pressure off. Open well 2432 psi. Bring pump on line. 4.5 BPM @ 2570 psi 14.6 BPM @ 3022 Shut down pump ISIP 2600 psi 5 min 2537 psi 10 min 2496 psi 15 min 2480 psi Shut well in.					
19:30	21:30	2.00	RD HES					
21:30	21:30	0.00	Flow well to PTS flow Back equipment. 2500 psi start flowing well back to tank farm.					
21:30	6:00	8.50	Wellhead pressure 2050 psi start flowing well back.					
21:30	21:30	0.00	Start flowing @ 4/128 choke at 2490 increase choke sowly to 32/128 From 2130 to 0015 pressure went to 0 psi flow back 59 bbls total fulld.					
			Shut well in pressure bluid to 2100 psi in 30 mins Open 32/128 choke went to 0 psi in 15 mins. 0300 well shut in ,let pressure build up 2050 psi.					

Exec Summary: MIRU HES fac Equipment.Peak deliver 650 bbls 9.8# Brine. Pump Breakdown,

Present Oper: Flow back well

24 Hr Forecast: Flow test well , MIRU Coil tbg unit to Blow down w/ N2