

Maintenance sheet version 9 for accumulation area (single mast, two levels)

Station name	CEN
People present	
Purpose	Maintenance / installation / take-down / quick visit / emergency
Date	

Notes: 2xSR50 membrane shipped, replace if time allows
 1xlufft assembly mount shipped to use on the upper lufft
 1xthermistor extension kit (2xthermistor, 1xpower), incl. 48mm mast and alu conn
 shipped (Chris knows)

AWS to do list		Check after maintenance			
Part	Shipped? (Y/N)	Replaced? (Y/N)	Number shipped/arrival	Number departure	
Radiometer	N				Clean? Y / N
Iridium modem IMEI number	N	Y	300534062419150	300534062418810	(REUSED - NOT NEW)
Inclinometer/compass	N		Attached to the radiometer? Y / N		
Satellite antenna	N				
Wind sensor upper	Y		Black box pointing toward the radiometer (i.e., along the boom)? Y / N		
Wind sensor lower	Y		Black box pointing same direction as the radiometer? Y / N		
Temperature / humidity assembly upper	Y/N		Fan spins? Y / N Sounds, OK? Y / N		
Temperature / humidity assembly lower	Y/N		Fan spins? Y / N Sounds, OK? Y / N		
Sonic ranger upper	Y/N		Old sensor with new membrane? Y / N		
Sonic ranger lower	Y/N		Old sensor with new membrane? Y / N		
Thermistor string	N				
Solar panel	Y		Clean? Y / N NB: is not effective when partially covered		
GPS antenna	N		At top of logger enclosure? Y / N		
Data logger	N		CR1000 or CR1000X?		
Logger enclosure	N		Replaced (including everything inside)? Y / N New desiccant bags? Y / N		
Battery box	Y		New box? Y / N New desiccant bags? Y / N		
Mast extension inserted?	N		How many inserted? How long? Notes:		
Mast	Y		New mast? Y / N New sensor boom? Y / N		

CEN

Metadata maintenance

	Arrival	Departure
Time difference between logger clock and UTC ($\pm$ mm:ss)		0
Download data to PC and/or change SD card (wait for green light)	(Y) / N	Y / N
Name of logger program		
Screen dump of values in fast scan mode	(Y) / N	Y / N
Photos of mast, sensors, logger box wiring etc. (more is better)	Y / N	Y / N
Mast tilt towards radiometer (- if looking up)	0 °	-1 °
Mast tilt across boom looking from radiometer (- if clockwise)	(zero) 0 °	0 °
Upper boom direction with radiometer relative to north	170 ° true/magn.	180 ° true/magn.
Lower boom perpendicular to upper boom. If not, measure.	(Y) / N °	(Y) / N °
Box on upper wind sensor exactly same direction as radiometer? If not, measure.	(Y) / N °	(Y) / N °
Box on lower wind sensor exactly same direction as radiometer? If not, measure.	(Y) / N °	(Y) / N °
Upper temperature / humidity height (bottom of casing – surface)	315 cm	426 cm
Lower temperature / humidity height (bottom of casing – surface)	185 cm	295 cm
Upper sonic ranger height (bottom of casing – surface)	221 291 cm	385 cm
Lower sonic ranger height (bottom of casing – surface)	165 cm	255 cm
Length of thermistor string on surface from surface marking	not drilled in cm	8m / cm
Apparent damage to sensors? If yes, which?	Y / N	Y / N

Notes:

REUSED OLD UPPER BOOM BECAUSE RADIOMETER TOP THERM. RIGHT ATTACHED. ALL UPPER SENSORS REUSED, EXCEPT AT SURFACE SR50-U. LOWER SENSORS REPLACED. OLD TYPE 7-JXKVA (REUSED FROM OLD CEN STATION)

NOTE - BOOM DIAMETERS ARE DIFFERENT!

GPS MOUNT 0cm AT WAST MOUNT.

VERY NOTEWORTHY - OLD STATION SENT WITH SUCCESS ON ARRIVAL AND S.D. CARD HAD VALID DATA FOR TODAY, BUT WE HAVEN'T SEEN ~~Must do at next visit:~~ TRANSMISSIONS IN MONTHS. REPLACED ~~WAST~~ MODEM FROM CP1, ALSO SENDING WITH SUCCESS. IRIUM LED LIGHTS UP, INDICATING NO ANTENNA PROBLEM.

NO VISUAL DEFECTS ON STATION.

→ FASTSCANNING THE STATION WHILE ON ITS SIDE (TO TEST ALL SENSORS) GAVE A POSITIVE "SEND WITH SUCCESS" AFTER FORCE_TX. AFTER RAISING THE STATION, IT WOULD NOT TRANSMIT. I ATTEMPTED A FEW TIMES, THEN PULLED THE MODEM OFF THE VELCRO TO CHECK THE STATUS LEDS. WHICH WERE ALL GOOD - THEN IT SENT WITH SUCCESS. I REPEATED THIS CYCLE TWICE - WHILE ATTACHED TO VELCRO, IT FAILS, AND WHEN RESTING ON THE PLUGS, IT'S FINE. I ~~BAR~~ UNTIGHTENED AND TIGHTENED THE RECEIVE & TRANSMIT PINS ON THE LOGGER, AND THIS SEEMED TO WORK.