

Maintenance sheet version 10 for accumulation area (single mast, two levels)

Station name	DY2 2023
People present	APD, NBK, ZAV, AEU, JJ, Reinhard Drews, Gummert & Bjorn
Purpose	Maintenance / installation / take-down / quick visit / emergency
Date	19 JUN

Notes: Raise mast of needed

calib. date
March 20

AWS to do list		Check after maintenance			
Part	Shipped? (Y/N)	Replaced? (Y/N)	Number shipped/arrival	Number departure	
Radiometer	N	Y		131455	Clean? Y / N
Iridium modem IMEI number	N	N		300534063811780	
Inclinometer/compass	N	Y		Attached to the radiometer? Y / N	
Satellite antenna	N	N			
Wind sensor upper	N	N		Black box pointing toward the radiometer (i.e., along the boom)? Y / N	
Wind sensor lower	N	N		Black box pointing same direction as the radiometer? Y / N	
Temperature / humidity assembly upper	Y	Y		Fan spins? Y / N Sounds, OK? Y / N cannot hear	
Temperature / humidity assembly lower	Y	Y		Fan spins? Y / N Sounds, OK? Y / N	
Sonic ranger upper	Y	Y		Old sensor with new membrane? Y / N	
Sonic ranger lower	Y	Y		Old sensor with new membrane? Y / N	
Thermistor string	N	N			
Solar panel	N	N		Clean? Y / N NB: is not effective when partially covered	
GPS antenna	N	N		At top of logger enclosure? Y / N	
Logger box ID	N	N		CR1000 or CR1000X9 ID number: No	
Logger enclosure	N	N		Replaced (including everything inside)? Y / N New desiccant bags? Y / N	
Battery box	N	N		New box? Y / N New desiccant bags? Y / N	
Mast extension inserted?	Y	Y		How many inserted? How long? 150 cm Notes:	
Mast	N	N		New mast? Y / N New sensor boom? Y / N	

Station name	DY2 2023
Date	14 JUN APA, NBE, ALY BAY, JJ, Reinhard Drums

Metadata maintenance

	Arrival	Departure
Time difference between logger clock and UTC ($\pm$ mm:ss)	-00:46	-00:46 (same)
Download data to PC and/or change SD card (wait for green light)	Y/N	Y/N
Name of logger program	GC-Net v2	GC-Net v2.4
Screen dump of values in fast scan mode	Y/N	Y/N
Photos of mast, sensors, logger box wiring etc. (more is better)	Y/N	Y/N
Mast tilt towards radiometer (- if looking up)	-2°	same °
Mast tilt across boom looking from radiometer (- if clockwise)	-1°	same °
Upper boom direction with radiometer relative to north	0° (true/magn.)	0° (true/magn.)
Lower boom perpendicular to upper boom. If not, measure.	Y/N 0°	Y/N 0°
Box on upper wind sensor exactly same direction as radiometer? If not, measure.	Y/N 0°	Y/N 0°
Box on lower wind sensor exactly same direction as radiometer? If not, measure.	Y/N 0°	Y/N 0°
Upper temperature / humidity height (bottom of casing – surface)	324 cm	484 cm
Lower temperature / humidity height (bottom of casing – surface)	207 cm	371 cm
Upper sonic ranger height (bottom of casing – surface)	284 cm	446 cm
Lower sonic ranger height (bottom of casing – surface)	167 cm	324 cm
Length of thermistor string on surface from surface marking	N/A cm	N/A cm
Apparent damage to sensors? If yes, which?	Y/N	Y/N

Notes:

logger box OS: 0502

→ inclinometer not working

Mast top to middle of upper boom (axis center): 11.0 cm

AWSS: Rover 16.7 cm bottom of 90° mount to bottom of ^{old} logger box
same → section of mast

Must-do at next visit:

