

Maintenance sheet version 10 for accumulation area (single mast, two levels)

Station name	DY2
People present	APA, JJ, ARV, BAV + Anders Debel Hansen, Frederik Svanborg
Purpose	Maintenance / installation / take-down / quick visit / emergency
Date	20/5-2024

Notes: Also installing SnowFox + Windmill, DE Program: "Jordan Kalder" filming

AWS to do list		Check after maintenance			
Part	Shipped? (Y/N)	Replaced? (Y/N)	Number shipped/arrival	Number departure	
Radiometer	N	N	131455		Clean? Y / N
Iridium modem IMEI number	N	300534053811780			
Inclinometer/compass	N	N	Attached to the radiometer? Y / N		
Satellite antenna	N	N			
Wind sensor upper	N	N	Black box pointing toward the radiometer (i.e., along the boom)? Y / N		
Wind sensor lower	N	N	Black box pointing same direction as the radiometer? Y / N		
Temperature / humidity assembly upper	N	N	Fan spins? Y / N Sounds, OK? Y / N		
Temperature / humidity assembly lower	N	N	Fan spins? Y / N Sounds, OK? Y / N		
Sonic ranger upper	Y	Y	Old sensor with new membrane? Y / N		
Sonic ranger lower	Y	Y	Old sensor with new membrane? Y / N		
Thermistor string	Y	Y			
Solar panel	N	N	Clean? Y / N NB: is not effective when partially covered		
GPS antenna	N	N	At top of logger enclosure? Y / N		
Logger box ID	Y	NOT CHANGED	CR1000 or CR1000X? ID number:		
Logger enclosure	Y	N, but grounded	Replaced (including everything inside)? Y / N New desiccant bags? Y / N		
Battery box	N	N	New box? Y / N New desiccant bags? Y / N		
Mast extension inserted?	Y	N	How many inserted? How long? Notes: 1/		
Mast	N		New mast? Y / (N) New sensor boom? Y / (N)		

Station name	DY2
Date	20/5 - 2024

Metadata maintenance

	Arrival	Departure
Time difference between logger clock and UTC ($\pm$ mm:ss)	+ 00:08	+ 00:08
Download data to PC and/or change SD card (wait for green light)	☒ Y / N	Y / N
Name of logger program	GCNet 2.4	GCNet v.2.6
Screen dump of values in fast scan mode	☒ Y / N	☒ Y / N
Photos of mast, sensors, logger box wiring etc. (more is better)	☒ Y / N	☒ Y / N
Mast tilt towards radiometer (- if looking up)	-1°	-1°
Mast tilt across boom looking from radiometer (- if clockwise)	0°	0°
Upper boom direction with radiometer relative to north	~ 0° true/magn.	0° true/magn.
Lower boom perpendicular to upper boom. If not, measure.	☒ Y / N	☒ Y / N
Box on upper wind sensor exactly same direction as radiometer? If not, measure.	☒ Y / N	☒ Y / N
Box on lower wind sensor exactly same direction as radiometer? If not, measure.	☒ Y / N	☒ Y / N
Upper temperature / humidity height (bottom of casing – surface)	cm	cm
Lower temperature / humidity height (bottom of casing – surface)	~ 325 cm	= cm
Upper sonic ranger height (bottom of casing – surface)	cm	cm
Lower sonic ranger height (bottom of casing – surface)	~ 278 cm	= cm
Length of thermistor string on surface from surface marking	N/A - cm	cm
Apparent damage to sensors? If yes, which?	☒ Y / N	Y / N

Notes:

Luftt second rib for top
 snowboard placed 2m clockwise from 2023
 at 10m dist from mast, height of stake 179 cm
 GNSS on mast 10,5 cm from mast connection to bottom of mount

Must-do at next visit:

thermistor tube 184 cm above surface