

Maintenance sheet version 10 for accumulation area (single mast, two levels)

Station name	DYE2
People present	HGTJA, APA, BAU, ARU, Elie Schlager, FALO, Johann, Arctar
Purpose	Maintenance/ installation / take-down / quick visit / emergency
Date	12 May 2025

Notes: -80C, some wind, landed on RIVEN runway
blowing snow

AWS to do list		Check after maintenance			
Part	Shipped? (Y/N)	Replaced? (Y/N)	Number shipped/arrival	Number departure	
Radiometer	N	N			Clean? Y / N
Iridium modem IMEI number	N	N			
Inclinometer/compass	N	N	Attached to the radiometer? (Y) / N		
Satellite antenna	N	N			
Wind sensor upper	Y	Y	Black box pointing toward the radiometer (i.e., along the boom)? (Y) / N		
Wind sensor lower	Y	Y	Black box pointing same direction as the radiometer? (Y) / N		
Temperature / humidity assembly upper	Y (Lufft)	Y	Fan spins? (Y) / N Sounds, OK? Y / N		
Temperature / humidity assembly lower	Y (Lufft)	Y	Fan spins? Y / (N) Program said fan wasn't spinning Sounds, OK? Y / N		
Sonic ranger upper	Y	Y	Old sensor with new membrane? Y / N		
Sonic ranger lower	Y	Y	Old sensor with new membrane? Y / N		
Thermistor string	PVC tube Ext. cable				
Solar panel	N Y	Y	Clean? (Y) / N Jakobs GNSS solution has new panel NB: is not effective when partially covered installed		
GPS antenna	N	N	At top of logger enclosure? Y / N		
Logger box ID	N	N	CR1000 or CR1000X? ID number:		
Logger enclosure	N	N	Replaced (including everything inside)? Y / (N) New desiccant bags? (Y) / N		
Battery box	N	N	New box? Y / (N) New desiccant bags? Y / (N)		
Mast extension inserted?	Y	Y	How many inserted? How long? Notes: old mast had to be cut short		
Mast	N	N	New mast? Y / (N) New sensor boom? Y / (N)		

Station name	DYE2
Date	NETJA, APA, PAT, AKU, ES, FALO

Metadata maintenance

	Arrival	Departure
Time difference between logger clock and UTC ($\pm$ mm:ss)	-00:03	00:03
Download data to PC and/or change SD card (wait for green light)	☒ Y / N	N/A ☒ Y / N
Name of logger program	GNet-v2.6	= v2.6
Screen dump of values in fast scan mode	☒ Y / N	☒ Y / N
Photos of mast, sensors, logger box wiring etc. (more is better)	☒ Y / N	☒ Y / N
Upper boom direction with radiometer relative to north	☒ true/magn.	☒ true/magn.
Lower boom perpendicular to upper boom. If not, measure.	☒ Y / N	☒ Y / N
Box on upper wind sensor exactly same direction as radiometer? If not, measure.	☒ Y / N	☒ Y / N
Box on lower wind sensor exactly same direction as radiometer? If not, measure.	☒ Y / N	☒ Y / N
Upper temperature / humidity height (bottom of casing – surface)	317 cm	450 cm
Lower temperature / humidity height (bottom of casing – surface)	191 cm	325 cm
Upper sonic ranger height (bottom of casing – surface)	273 cm	403 cm
Lower sonic ranger height (bottom of casing – surface)	155 cm	284 cm
Length of thermistor string on surface from surface marking DVC tube	69 cm	cm
Apparent damage to sensors? If yes, which?	☒ Y / N	☒ Y / N

Notes: Snow board stake ARR: 54 cm / Dep snow stake 153 cm
 Snow depth at snowboard: 129 cm / DVC pipe 265 cm
 One cable of the battery box was snapped during digging
 Box is taken back to SFJ for fixing
 - Jacobs GNSS solution was installed

Must-do at next visit:

Battery box either new or fixed one