

Maintenance sheet version 10 for ablation area (tripod, one level)

Station name	KAN_U 2023
People present	APA, JJ, BAV, ABU, Reinhard Drews (Eggert + Neso)
Purpose	Maintenance / installation / take-down / quick visit / emergency
Date	8 JUNE 2023 9:30 LT

Notes: Make mast solution, but promise v2 instrumentation and GC net batterybox

AWS to do list		Check after maintenance			
Part	Shipped (Y/N)	Replaced? (Y/N)	Number shipped/arrival	Number departure	
Radiometer	N	67 <i>Y</i>	202705 <i>calib Nov 2020</i>	213270	Clean? <i>Y</i> /N <i>Calib date March 2023</i>
Ablation hose assembly	N				No air in hose and bladder half full? Y/N
Iridium modem IMEI number (inside loggerbox)	Y		S: 30053406245410		<i>external still in use</i>
Inclinometer/compass	N	<i>Y+N</i>	Attached to the radiometer? Y / N <i>#1 old inclin. still in use</i> <i>#2: Inside, but not used due to v.2</i>		
Satellite antenna	N				
Wind sensor	Y	<i>104 axis cm</i>	Black box pointing toward the radiometer (i.e., along the boom)? Y / N		
Temperature / humidity assembly	Y		Fan spins? Y / N Sounds, OK? Y / N		
HygroClip T/hum assembly	N		NB: Rotronics (Y / N) could have a 40 °C offset. New or old type? NB: Lufft sensor (Y / N)		
Sonic ranger on AWS	Y	<i>56 cm</i>	Old sensor with new membrane? Y / N		
Sonic ranger on stake(s)	Y	<i>0 cm</i>	Old sensor with new membrane? Y / N NB: make sure not being buried next winter		
Thermistor string	Y				
Solar panel	Y		Clean? Y / N NB: is not effective when partially covered		
GPS antenna (inside loggerbox)	Y		At top of logger enclosure? Y / N		
Logger box ID	T2-0002		CR1000 or CR1000X? ID number:		
Multiplexer	N		Clicking during measurement cycle? Y / N		
Logger enclosure (v2)	Y		Replaced (including everything inside)? Y / N New desiccant bags? Y / N		
Battery box	Y		New box? Y / N New desiccant bags? Y / N		
Stakes	Y		New one(s) drilled in? Y / N Length of new stake(s) 8 m? Y / N Bottom plugged to reduce melt-in? Y / N		
New complete mast set, incl 1xboom	Y		New tripod? Y / N New sensor boom? Y / N		

Station name	KAN_U 2023
Date	8 JUNE 2023

Metadata maintenance

	Arrival	Departure
Time difference between logger clock and UTC ($\pm$ mm:ss)	-03:00	
Download data and/or change CF/SD Card (wait for green light)	Y / N	Y / N
Name of logger program	Promice2015e.Cr1	Promice 2022 v1.1
Screen dump of values in fast scan mode	☒ Y / N	☒ Y / N
Photos of tripod, sensors, logger box wiring etc. (more is better)	☒ Y / N	Y / N
Mast tilt towards radiometer (- if tilting towards anemometer)	0 °	+ 0.5 °
Mast tilt across boom looking from radiometer (- if clockwise)	0 °	0 °
Boom direction relative to north	° true/magn.	° true/magn.
Box on wind sensor exactly towards mast? If not, measure.	☒ Y / N	☒ Y / N
Radiometer exactly aligned with inclinometer? If not, measure.	tilt - 1° Y / N radiom 0°	☒ Y / N
Temperature / humidity height (bottom of casing – surface)	54 cm	330 cm
Stake assembly standing?	Y / N / (sort of)	Y / N / sort of
Free length of stake (if 3: outer, holding boom with sonic ranger)	45° tilt 115 cm	cm
Free length of stake 2 (if 3: middle)	45° tilt 125 cm	cm
Free length of stake 3 (if 3: outer, without sonic ranger)	cm	cm
Height of ablation bladder fluid level above the ice surface	cm	cm
Vertical difference in surface height (at station – at hose) (approx.)	cm	cm
Length of thermistor string on surface from surface marking	0 cm from 1st thermistor	cm
Apparent damage to sensors? If yes, which?	☒ Y / N	Y / N

Notes:

sardugi : 3-4 cm

solar panel partly buried

GPS mount bottom to mast connector 9cm

Young wind sensor broken (head off)

NB : We forgot to refill the thermistor string hole with snow

— hangs in hole, but closed at to
top-most thermistor placed at surface

Must do at next visit:

lower SPDA 240 cm

upper SPDA 140 + (280 - 60)

Radiometer bottom of casing : 330 cm

Radiometer : 357 cm