

Maintenance sheet version 9 for accumulation area (single mast, two levels)

Station name	NASA_E
People present	APA, CLAN, PHO, OEW + Kiddi & Bjarni
Purpose	Maintenance / <u>installation</u> / take-down / quick visit / emergency
Date	26/5-2022

Notes: MV6 - NAE 9:15 - 10:55 Local time = UTC
 NAE - MV6 19:15 -

AWS to do list		Check after maintenance			
Part	Shipped? (Y/N)	Replaced? (Y/N)	Number shipped/arrival	Number departure	
Radiometer	Y		213288	— 11 —	Clean? <u>Y</u> / N
Iridium modem IMEI number	Y		300534063815700	— 11 —	
Inclinometer/compass	Y		Attached to the radiometer? <u>Y</u> / N		
Satellite antenna	Y				
Wind sensor upper	Y		Black box pointing toward the radiometer (i.e., along the boom)? <u>Y</u> / N		
Wind sensor lower	Y		Black box pointing same direction as the radiometer? <u>Y</u> / N		
Temperature / humidity assembly upper	Y		Fan spins? Y / N Sounds, OK? Y / N		
Temperature / humidity assembly lower	Y		Fan spins? Y / N Sounds, OK? Y / N		
Sonic ranger upper	Y		Old sensor with new membrane? Y / <u>N</u>		
Sonic ranger lower	Y		Old sensor with new membrane? Y / <u>N</u>		
Thermistor string	Y				
Solar panel	Y		Clean? <u>Y</u> / N NB: is not effective when partially covered		
GPS antenna	Y		At top of logger enclosure? Y / N ↳ separate instructions		
Data logger	Y		CR1000 or <u>CR1000X</u> ?		
Logger enclosure	Y		Replaced (including everything inside)? Y / <u>N</u> New desiccant bags? Y / N <u>NONE</u>		
Battery box	Y		New box? <u>Y</u> / N New desiccant bags? Y / <u>N</u> <u>None</u>		
Mast extension inserted?	N		How many inserted? How long? Notes:		
Mast	Y		New mast? <u>Y</u> / N New sensor boom? <u>Y</u> / N <u>10 cm ALU</u>		

196
165
355
361

Metadata maintenance

	Arrival	Departure
Time difference between logger clock and UTC ($\pm$ mm:ss)		0
Download data to PC and/or change SD card (wait for green light)	Y / N	Y / N
Name of logger program		pic
Screen dump of values in fast scan mode	Y / N	Y / N
Photos of mast, sensors, logger box wiring etc. (more is better)	Y / N	Y / N
Mast tilt towards radiometer (- if looking up)	°	0°
Mast tilt across boom looking from radiometer (- if clockwise)	°	0°
Upper boom direction with radiometer relative to north <i>positively south</i>	° true/magn.	150° true/magn.
Lower boom perpendicular to upper boom. If not, measure.	Y / N °	Y / N °
Box on upper wind sensor exactly same direction as radiometer? If not, measure.	Y / N °	Y / N °
Box on lower wind sensor exactly same direction as radiometer? If not, measure.	Y / N °	Y / N °
Upper temperature / humidity height (bottom of casing – surface)	cm	384 cm
Lower temperature / humidity height (bottom of casing – surface)	cm	277 cm
Upper sonic ranger height (bottom of casing – surface)	cm	361 cm
Lower sonic ranger height (bottom of casing – surface)	cm	240 cm
Length of thermistor string on surface from surface marking	cm	400 cm
Apparent damage to sensors? If yes, which?	Y / N	Y / N

Notes:

Radiometer bottom 370

CLAN will write up comments about problematic battery wiring elsewhere – was not easy

→ surface to bottom of geoprecision converted – thermistor was stretched

Must do at next visit:

Density : every 10 cm on mast core 2m
every 20-60 cm on therm. core 10m
every 10cm in pit incl. temp.

Problems : 14 dom with 2m interval around dens. pit

coverage : ~~34 cm~~ 34 cm to pss

see
APA
field book
for number

Go. Met NASA-E 26/5-22
OLD

Mast lift picture x2 (slightly tilting)

Lower SR50 60cm

Upper SR 50 154cm

Ticow to bottom of screen 109cm  ← point meas.

Tipper 200cm

Bulb reasonably cracked both sides 174cm

Licor - middle of boom 182cm

Windlower OK 122cm

Windupper tail broken off 220cm

Solar panel lower bottom 200cm

Old NASA-E looks in good condition

meas. ~~15V~~ 14.5V

Mem card only 256MB

Data downloaded (6 yrs)

GPS data looked good until today (?)

No light on the "modem"

Left station to keep recording

