

TAS-U

13/8-2015

Taken down

T-Hum casing $\rightarrow 20^\circ$ Sonic ranger AWS $\rightarrow 283$

Boom direction

Mast tilt 1 $+9^\circ$ Mast $\rightarrow$ 2 -8°

Free length stake outer Sonic ranger 413

middle 400

outer 430

T-string length

340 from lam

Abl. hose

made

2305 slung frame

Abl. hose fluid R63

Vertical diff surface H $\sim 0m$ Surface irregularities $\sim 70cm$

Stake assembly fallen down

Ablation hose casing door broken

