sanas South African National Accreditation System

NON-CONFORMANCE, CORRECTIVE ACTION AND CLEARANCE REPORT

SANAS No.:

Organisation Name: Azureshy PTY LTD

NC Report Number: NC12-2026

Area/Scope Assessed: Management Review

Assessor / Inspector / Expert: Mapanya TMJ

PART 1: DETAILED OBSERVATION

It was noted that there is no additional process/procedure detailing the implementation of the requirement 6.4

Signed (Representative): Gnaldra

Signed (Team Leader / Inspector): Mapanya

MAJOR: ☑ MINOR: ☐

Reference No. of relevant Guide / Standard / Requirement: 6.4

Date: 10/02/2026

PART 2: ROOT CAUSE ANALYSIS

(Provide an analysis of the extent and cause of the nonconformity)

The required processes for clause 6.4 were not fully written down. The root-cause was incomplete system documentation

PART 3: CORRECTIVE ACTION TAKEN

(Clearly indicate what corrective action was taken, and attach supporting evidence of implementation)

A new document was drafted - ASMF 6.3 proc - detailing the additional processes of the implementation of 6.4 Requirement. A Memo no. 003 was sent out to all Personnel

Date: 11/02/2026

Signed (Representative): Gnaldra

PART 4: CORRECTIVE ACTION VERIFIED AND CLEARED

(Comment on whether the corrective action is sufficient and appropriate)

Addressed

Date: 1/02/26

Signed: Assessor / Inspector/Expert: Mapanya

PART 5: FOLLOW-UP AT NEXT ASSESSMENT

(Comment on the implementation of the corrective actions)

Date:

Signed: Assessor / Inspector/Expert:


©SANAS

AS001MF

07/25

ROOT CAUSE ANALYSIS FORM

IRQ NO: NC12 - 2026 T



.....

SUPERVISOR

AS004MF 07/25

BRAINSTORMING FORM

IRQ no: NC12-2026T

Brainstorming team

Nosipho Hlongwane, Lilo Photo, Sifiso Nyambi, Abonathi Jama, Keitumetse Maleka

Problem Statement: There was no procedure detailing the implementation that covers critical aspects from the moment equipment is received in the laboratory including equipment calibration, instrument maintenance (eg L.C.

Why 1 Why was there no Procedure detailing / specifically covering the Critical aspects from the moment equipment is received in the laboratory?

A note was made in the Lab's procedures that deals with equipment. This was thought to have satisfied the 6.4. requirement, as a result no detailed document was created.

Supervisor:

AzurESky

MEMORANDUM

MEMO no: MO -003

Department: Management Review

Compiler: Lilo Dorothy Photo

Title: Creation of a procedure detailing implemention of 6.4 requirements

Date: 10 January 2026

TO : ALL LABORATORY and PREPARATION STAFF

Please be adviced that there is now a procedure for inhouse/ the implementation of 6.4 that covers critical aspects of equipment from the moment it is received in the laboratory including equipment calibration, instrument maintenance log e.t.c.

Thank you for your attention to this matter.

NAME	SURNAME	POSITION	SIGNATURE
Lilo ~~Photo~~ Dorothy	Photo	Lab Analyst	
Jifiso	Myambi	Lab Manager	
Tshepo	Mapongwa	Lab Supervisor	Mapongwa
Nosipho	Mlangwane	Lab Analyst	
Abenathi	Jama	Lab Analyst	
Keitumetse	Maleka	Lab Analyst	Kmaleka

AzureSky		
	Hard coal sample preparation procedure	Document no: AS001IW
Compiled by:	Sifiso Nyambi - Laboratory Manager	
Approved by:	Nonhlanhla Msibi - Operations Manager	

8. Air-dry the sample in an oven ≤ 40 °C for ≤4 hours.
9. Pulverise the entire sample.
10. Transfer the sample into the 210L drum, strap the drum onto the mixer and homogenise for 4 hours.
11. Finally, take increments of ±600g in a pan. Use the flat heap method to take portions from 600g and transfer into ~100g bottles for packaging.
12. In the process take 10 random samples which will be used for homogeneity check and validation of GA parameters.
13. Take about 50 samples for PT and label them. The rest of the samples shall be used as CRMs, and they too should be labelled.

- **Note: These 10 bottles shall be kept in storage under the same conditions as the CRMs, they will be used to monitor stability of the samples.**
- **It is also worth noting that the top nominal size of all samples received by the lab shall not be >50mm.**

Note: Ensure all equipment and materials used are verified against factory specifications and logged in the equipment register prior to use. Calibrations (where necessary) and verification of equipment are to be attended prior to use. Calibration services shall only be sourced from ISO/IEC 17025 accredited labs. Verification certificates from manufacturers are accepted for new equipment provided to address traceability.(ISO 17025: Clause 6.4.)

4.2. For Hardgrove and Abrasive index (Eskom Method).

A minimum mass of 300 kg is required:

- Air dry the entire sample, until visibly dry.
- Cone and quarter the entire sample, take two opposites for PT and then cone and quarter the other two opposites. From this take two opposites and add to the first two PT opposites. Approximately 225 kg and 75 kg should be obtained for AI and HGI, respectively.

AzurESky ensure quality of test	Equipment Management		
	Document no: ASMF 6.3 Proc		
	Compiled by:	Tshepo Maponya - Laboratory Supervisor	
	Approved by:	Nonhlanhla Msibi - Operations Manager	

1. Purpose & Scope

This procedure outlines the selection, identification, calibration, and maintenance of all laboratory equipment. This applies to all "critical equipment"—any hardware or software that can significantly influence the accuracy of laboratory results.

2. Selection and Verification

Before any equipment is placed into service (whether it is brand new or returning from repair), it must be verified.

- **Action:** The lab Manager/Supervisor compares the equipment's performance against the manufacturer's specifications or the laboratory's method requirements.
- **Record:** Identification & Verification results are noted in the **Equipment Register (ASMF 6.3 Equipment Register).**

3. Identification and Labelling

All equipment listed in the register shall be uniquely identified with a dedicated equipment number.

- **Calibration Labels:** Equipment must be labelled with its calibration status, indicating the **date of last calibration** and the **due date for the next calibration,** where necessary.

4. Handling, Transport, and Storage

To prevent contamination, damage, or deterioration:

- Equipment must be used only by authorized personnel.
- Sensitive instruments (e.g., balances) must be protected from vibrations and extreme temperature shifts.
- If equipment is transported outside the lab, it must be re-verified upon return before being used for testing.