sanas South African National Accreditation System

NON-CONFORMANCE, CORRECTIVE ACTION AND CLEARANCE REPORT

SANAS No.: T1195

Organisation Name: AZURESKY PTY (LTD)

NC Report Number: NC04

Area/Scope Assessed: Coal Testing

Assessor / Inspector / Expert: NCHILZA

PART 1: DETAILED OBSERVATION

The Control Chart for Volatile Matter (27/08/25 – 3/10/25) had ten Consecutive points below the mean and no action was taken

b) The rules presented for control chart does not form part of the system as they are not dated or referenced form the Lab procedure (Ensuring validity of Results

Signed (Representative):

Signed (Team Leader / Inspector):

MAJOR: [X] MINOR: [ ]

Reference No. of relevant Guide / Standard / Requirement: ISO/IEC 17025 7.7

Date: 08/04/26

PART 2: ROOT CAUSE ANALYSIS

(Provide an analysis of the extent and cause of the nonconformity)

PART 3: CORRECTIVE ACTION TAKEN

(Clearly indicate what corrective action was taken, and attach supporting evidence of implementation)

Date:

Signed (Representative):

PART 4: CORRECTIVE ACTION VERIFIED AND CLEARED

(Comment on whether the corrective action is sufficient and appropriate)

Date:

Signed: Assessor / Inspector/Expert:

PART 5: FOLLOW-UP AT NEXT ASSESSMENT

(Comment on the implementation of the corrective actions)

Date:

Signed: Assessor / Inspector/Expert:

©SANAS