# LiPo Battery & Charger Testing Report

# Reported by:

Mohammed Azab Nada Mahomud

**Date:** 05. Feb. 2025

Version: 1.0

#### **Table of Contents**

- 1. Introduction
- 2. Equipment & Components
- 3. Testing Procedure
  - o Battery Inspection
  - Charging Process
  - Load Testing
  - Connection to Car
- 4. Test Results & Observations
- 5. Safety Guidelines & Best Practices
- 6. Conclusion & Recommendations

### 1. Introduction

#### **Objective**

This document outlines the testing procedures for a LiPo battery and charger to verify their functionality and ensure compatibility with the target vehicle. It also addresses connection differences and possible solutions.

#### **Scope**

- Checking battery health and charging performance.
- Measuring battery behavior under load conditions.
- Ensuring compatibility with the vehicle's power system.

# 2. Equipment & Components

Component	Model/Specification	Description
Battery	Zeee 7200mAh LiPo	LiPo, 7.4V 7200mAh
Charger	iMax B6 80W LiPo Balance Charger	Supports LiPo, 80W

# 3. Testing Procedure

### 3.1 Battery Inspection

- Checked for physical damage (swelling, leakage, broken connectors).
  Observation: No physical damage detected.
- Measured battery voltage before charging.

# **3.2 Charging Process**

- 1. Connected the charger to a power source.
- 2. Set charging parameters (battery type, voltage, current).
- 3. Connected the battery and initiated charging.
- 4. Monitored the charging process (temperature, charge time).
- 5. Verified that the battery reached full charge without issues.

# 3.3 Load Testing

- Discharged the battery under controlled conditions.
- Measured voltage drop and current draw.
- Ensured the battery maintained stable output within safe limits.

#### 3.4 Connection to Car

- Attempted to connect the battery to the vehicle.
- **Observation:** The battery connector differs from the car body connector, requiring a replacement connector.

#### 4. Test Results & Observations

- Charging time and efficiency were satisfactory.
- Battery performed well under load.

- No malfunctions or critical issues were observed.
- The main issue encountered was the incompatibility of the battery connector with the car body, necessitating a new connector for proper integration.

# 5. Safety Guidelines & Best Practices

- Always charge in a fireproof area.
- Do not overcharge or discharge below safe limits.
- Ensure proper polarity and secure connections.
- Store batteries at recommended voltage levels when not in use.

#### 6. Conclusion & Recommendations

- The battery and charger performed as expected with no faults.
- The main issue identified was the mismatch between the battery and car body connectors.
- **Recommendation:** Purchase and replace the connector to ensure compatibility.
- Consider future upgrades or alternative battery models with pre-matching connectors to avoid similar issues.