
PC GUI
STM32 (IDLE)
CONNECT
OK
NEW
OK:BOARD:.....
IN_PROGRESS
MOVE:X:4
OK:BOARD:....X....
MOVE:O:4
NACK:OCCUPIED
state unchanged
more moves omitted
MOVE:X:6
WIN:X:O.XOX.X..
GAME_OVER
MOVE:O:1
NACK:NOGAME
DISCONNECT
OK
IDLE