
Position stage peaks and participant-bootstrap intervals (exploratory)
PSM-stage
Within occurrence
Task A / PSM L
drop ring
grab ring
place ring
reach ring
transfer ring
unsupported
n=11
n=11
n=11
n=11
n=11
n=11
n=11
n=11
n=11
n=11
−2
−1
0
1
2
Peak lag (s); positive = gaze leads
Task A / PSM R
drop ring
grab ring
place ring
reach ring
transfer ring
unsupported
n=11
n=11
n=11
n=11
n=11
n=11
n=11
n=11
n=11
n=11
−2
−1
0
1
2
Peak lag (s); positive = gaze leads
Task C / PSM L
pull through and cinch
reach string
threading string through tower
wrap around psm
n=11
n=11
n=11
n=11
n=8
n=6
n=11
n=11
−2
−1
0
1
2
Peak lag (s); positive = gaze leads
Task C / PSM R
pull through and cinch
reach string
threading string through tower
wrap around psm
n=11
n=11
n=11
n=11
n=8
n=6
n=11
n=11
−2
−1
0
1
2
Peak lag (s); positive = gaze leads
Same lag scale in every panel; triangles = boundary estimates. Different modes can have different participant/record support; no multiple-comparison correction.