HW 2 Master Script

Table of Contents

Initialize	1
Run Problem scripts and publish them	1
Publishing tools and support code	2

Initialize

```
if ispc
    addpath('C:\Users\John\Documents\ASEN5010\tools')
end
clear all
clc
% Cell array to track what functions are used, so they can be published
% later
global function list;
function_list = {};
% publishing options
pub opt.format = 'pdf';
pub_opt.outputDir = '.\html';
pub opt.imageFormat = 'bmp';
pub_opt.figureSnapMethod = 'entireGUIWindow';
pub_opt.useNewFigure = true ;
pub opt.maxHeight = Inf;
pub opt.maxWidth = Inf;
pub_opt.showCode = true;
pub_opt.evalCode = true;
pub_opt.catchError = true;
pub_opt.createThumbnail = true;
pub opt.maxOutputLines = Inf;
```

Run Problem scripts and publish them

```
% Problem 1: S&J, Problem 3.11
publish('HW2_P1', pub_opt);

% Problem 4: S&J, Problem 3.12
publish('HW2_P4', pub_opt);

% Problem 5: S&J, Problem 3.13
publish('HW2_P5', pub_opt);

% Problem 6: S&J, Problem 3.14
publish('HW2_P6', pub_opt);
```

Publishing tools and support code

```
pub_opt.outputDir = '.\tools';
pub_opt.evalCode = false;

%Publish all used functions
function_list = ...
    [function_list; 'C:\Users\John\Documents\ASEN5010\tools\fcnPrintQueue'];
for idx = 1:length(function_list)
    publish(function_list{idx}, pub_opt);
end
```

Published with MATLAB® R2013b