




20mm thick x 90mm wide
50mm tall handle
.2 layer 50% infill



Filament Run Out Sensor



Dual Gear Extruder



4020 NOCTUA Quiet Fan
Moves plenty of Air. The 4010 OEM fan was way to loud. Dual Parts Cooling Fans Capricorn Tubing Dual Strain Relief Bracket




This entire front body is ABS Plastic
It is rigid enough, but I would not trust it

My \$45 Chromoly Steel Lead Screw

4020 top end of z Beam

As you can see, trying to put any kind
of support in the back would be near
impossible.




Size of Power Supply

210mm

100mm



There is this bracket in the front on the Z Beam, the top two screws were a bit loose, 1 1/2 turns worth. Put some Red Loctite on the threds and retightened them. That might have been where I was getting the movement from. My dial indicator has about .0002 of movement now.



100mm width on power supply case