

FIELD INSPECTION REPORT

Date: 2026-06-12 10:00 AM

Equipment Tag: P-101A

Inspector: John Doe

Findings: Handheld sensor reads abnormal vibration.

Measured Vibration: 3.8 mm/s.

Warning: This exceeds the current SOP v2 limit of 3.0 mm/s.

Action: Submitted work order WO-9921.