




Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

Quality Layer Extruder Infill Solid Fill Support Platform Additions Cooling Temperature Speed Advanced Ooze Other Special GCode Notes

Layer Height 0.3000 mm

First Layer Height 0.3000 mm

First Layer Extrusion Width Percentage 100 %

☐ First Layer Solid Fill Extrusion Width Percentage 100 %

Outer Shell Extrusion Width Percentage 100 %

Inner Shell Extrusion Width Percentage 100 %

Infill Extrusion Width Percentage 90 %

Base Solid Fill Extrusion Width Percentage 100 %

Solid Fill Extrusion Width Percentage 100 %

Top Surface Solid Fill Extrusion Width Percentage 100 %

Bottom Surface Solid Fill Extrusion Width Percentage 100 %

Support Extrusion Width Percentage 100 %

Dimensional Compensation

XY Size Compensation for Contours 0.00 mm

XY Size Compensation for Holes 0.00 mm

☐ Elephant Foot Compensation

First Layer XY Size Compensation for Contours 0.00 mm

First Layer XY Size Compensation for Holes 0.00 mm

Flowrate

First Layer Flowrate 100.0 %

☐ First Layer Solid Fill Flowrate 100.0 %

Outer Shell Flowrate 100.0 %

Inner Shell Flowrate 90.0 %

Infill Flowrate 90.0 %

Base Solid Fill Flowrate 95.0 %

Solid Fill Flowrate 95.0 %

Narrow Solid Fill Flowrate 95.0 %

Top Surface Solid Fill Flowrate 120.0 %

Narrow Top Surface Solid Fill Flowrate 120.0 %

Bottom Surface Solid Fill Flowrate 120.0 %

Shrinkage Compensation

Scale Factor X 100.00 %

Scale Factor Y 100.00 %

Scale Factor Z 100.00 %

☐ Precise Z Height

Precise Z Height Layers 5

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

Type here to search (Ctrl + F)

Quality Layer Extruder Infill Solid Fill Support Platform Additions Cooling Temperature Speed Advanced Ooze Other Special GCode Notes

Shells

4.0

Maximum Shells Overlap Percentage

50

%

☐ Print Shells in Optimal Order

First Layer Solid Fill Pattern Type

 Lines☐ First Layer Shells

5.0

Shells Direction List

Orientation

CCW

Add

Remove

Scarf Joint

Scarf Joint Type

Contour and Hole

☒ Conditional Scarf Joint

Scarf Joint Angle Threshold

155

Deg

☐ Scarf joints around entire shell

Scarf Joint Length

20.0

mm

Scarf Joint Steps

10

Scarf Joint Start Height Ratio

0

%

☒ Scarf Joint for Inner Shells

Scarf Joint Speed Multiplier

100

%

☐ Spiral Vase Mode☒ Spiral Vase Mode Path Interpolation☐ Single Shell Surface Mode

Shell and Infill Order

Infill > Outer Shell > Inner Shell

☐ Print Parts in Same Order for Each Layer

Minimal Segment Length

0.100

mm

Merge Nearby Lines

0.100

mm

Minimal Part Size

100

%

☐ Only one shell on top surfaces

Conditional One Shell Top Surface (Min Width)

0.00

mm

Conditional One Shell Top Surface (Min Area)

0.00

mm²

Layer Start Point

Layer Start Point Type

Auto

Fixed Layer Start Point

0.00

mm

0.00

mm

☐ Seam Relative Positions

Place Seam on

Reflex or Convex Corner

☐ Allow Placing Seams on Non-Polygon Vertex☒ Avoid Placing Seams on Overhangs☐ Add inward movement at the end of the outer shell

Restore

Save As

Cancel

OK

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

Type here to search (Ctrl + F)

Quality

Layer

Extruder

Infill

Solid Fill

Support

Platform Additions

Cooling

Temperature

Speed

Advanced

Ooze

Other

Special

GCode

Notes

Primary Extruder

General

Extrusion Width

0.40

mm

☒ Retraction

Retraction Speed

40.0

mm/s

Retraction Material Amount

3.00

mm

Minimal Travel of Retraction

5.00

mm

Minimal Amount of Retraction

0.02

mm

Extra Restart Amount

0.00

mm

Restart Speed

25.0

mm/s

☐ Avoid Unnecessary Retraction in Support

Z Hop at Retraction

0.200

mm

Z Hop Type

Normal

Z Hop performed

All

Coasting

Coasting Distance

0.00

mm

☐ Apply Coasting on Grid Infill and Lines Solid Fill

Wipe

Outer Shell Wipe Distance

0.00

mm

Outer Shell Wipe Speed

50.0

mm/s

Wipe Nozzle for Support

0.00

mm

Wipe Nozzle for Infill

0.00

mm

Wipe Nozzle for Solid Fill

0.00

mm

Wipe Nozzle for Thin Wall

0.00

mm

☐ Retraction during Wipe

Retraction Amount before Wipe

0

%

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

Type here to search (Ctrl + F)

Quality Layer Extruder Infill Solid Fill Support Platform Additions Cooling Temperature Speed Advanced Ooze Other Special GCode Notes

Infill

Infill Extruder

Primary Extruder ▼

Infill Density

10 %

Infill Overlap

4 %

Infill Pattern Type

 Grid ▼☐ Fill Gaps in 100% Concentric Infill☐ Connect Infill Lines Endpoints☒ Use Lines Pattern in High Density Grid Infill Pattern

Infill Offset X

0.00 mm

Infill Offset Y

0.00 mm

Combine Infill Layers

1

Infill Outline Shells

0

☐ Fill Gaps in Infill Outline Shells☐ Print Solid Fill in 100% Infill

Infill Anchor Length Factor

0 %

Infill

Infill Minimal Width

0.05 mm

Infill Minimal Area

0.00 mm²☐ Adaptive Infill

Adaptive Infill Reduction Count

2

Infill Ratio Range

5 — 30 %

Adaptive Infill Layers

5

Adaptive Infill Inner Horizontal Expansion

0.80 mm

Adaptive Infill Minimal Width

3.00 mm

Infill Angle

Angle

0 Deg

45
135

Add Infill Angle

Remove Infill Angle

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

Type here to search (Ctrl + F)

Quality

Layer

Extruder

Infill

Solid Fill

Support

Platform Additions

Cooling

Temperature

Speed

Advanced

Ooze

Other

Special

GCode

Notes

Top and Down Solid Part

Base Solid Fill Layers

5

Solid Fill Layers

5

Base Solid Fill Pattern Type



Lines

Solid Fill Pattern Type



Lines

Solid Fill Outline Shells

0

Solid Fill Minimal Width

0.00

mm

Solid Fill Expansion

0.00

mm

Expand Solid Fill to Fill Small Hole

0.00

mm

☐ Use concentric filling for narrow solid fill parts

Monotonic Solid Fill

☐ Base Monotonic Solid Fill☐ Monotonic Solid Fill☐ Top Surface Monotonic Solid Fill

Top and Down Solid Fill Angle

Angle

0

Deg

45

135

Add

Remove

Top Surface Solid Fill Layers

0

Top Surface Solid Fill Pattern Type



Lines

Top Surface Solid Fill Expansion

0.00

mm

Conditional Top Surface Pattern Type (Min Width)

0.00

mm

Conditional Top Surface Pattern Type (Min Area)

0.00

mm²

Bottom Surface Solid Fill Layers

0

Bottom Surface Solid Fill Pattern Type



Lines

Bottom Surface Solid Fill Expansion

0.00

mm

☐ Ironing

Ironing Flowrate

5.0

%

Ironing Speed

10.0

mm/s

☐ Ironing Monotonic

Ironing Angle

90

Deg

Ironing Line Distance

0.00

mm

Ironing Inset

0.20

mm

Ironing Pattern

Rectilinear

☐ Small Area Solid Fill Flow Compensation

Small Area Solid Fill Flow Compensation Model

Edit



Restore

Save As

Cancel

OK

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

Type here to search (Ctrl + F)

Quality

Layer

Extruder

Infill

Solid Fill

Support

Platform Additions

Cooling

Temperature

Speed

Advanced

Ooze

Other

Special

GCode

Notes

Generate Support

All

Support

Dense Support

Adaptive Support

Support

Support Extruder

Primary Extruder

Support Type

Tree

☐ Generate Support Enforcer Only

Support Infill Type

Lines

Support Infill Outlines

0

Support Infill Outlines Extruder

Primary Extruder

Infill Ratio

30

%

Max Overhang Angle

45

Deg

Horizontal Offset

0.70

mm

Vertical Offset Top Layers

1

Vertical Offset Down Layers

1

Support Flowrate

100.0

%

Horizontal Expansion

0.00

mm

Solid Base Layers

0

Support Brim Width

2.0

mm

Interlaced Support Infill Angle

Angle

0

Deg

-45

Add

Remove

Other

Pillar Size

4.00

mm

☐ Add Sparse Connection☐ Generate Support under Small Floated Features

Support Expansion under Small Floated Features

1.00

mm

☐ Recreate Support after Modifier Boolean Operation☒ Use Lines Pattern in High Density Grid Support Infill Pattern

Tree Support

Tree Support Branch Diameter

2.00

-

15.00

mm

Tree Support Branch Angle

45

Deg

Tree Support Branch Density

30

%

Branch Diameter Double Outlines

3.00

mm



Restore

Save As

Cancel

OK

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

Type here to search (Ctrl + F)

Quality

Layer

Extruder

Infill

Solid Fill

Support

Platform Additions

Cooling

Temperature

Speed

Advanced

Ooze

Other

Special

GCode

Notes

Platform Addition

Skirt Only

Raft

Raft Extruder

Primary Extruder

Raft Offset

5.00

mm

Raft Gap from Model

0.15

mm

Second Layer Z Lift

0.00

mm

Raft Lines Type



Lines

☐ Keep Holes in Raft Structure

First Layer

Middle Layer

Surface Layer

First Layers

2

First Layer Speed

8.0

mm/s

Extrusion Width Percentage

200

%

Layer Height

0.5000

mm

First Layer Infill Ratio

33

%

First Layer Infill Angle

0

Deg

Skirt and Brim

Skirt/Brim Extruder

Primary Extruder

Skirt/Brim Speed

15.0

mm/s

Skirt/Brim Minimal Length

0.00

mm

Skirt Loop Lines

2

Skirt Offset Distance

0.01

mm

Skirt Layers

1

☐ Skirt - Print Outer Shell Before Inner Shell in the First Layer

Brim Type

Outer Only

Brim Loop Lines

10

Brim Offset Distance

0.00

mm

☐ Brim - Print Outer Shell Before Inner Shell in the First Layer☐ Raft Overrides

+ -



Restore

Save As

Cancel

OK

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

Type here to search (Ctrl + F)

Quality

Layer

Extruder

Infill

Solid Fill

Support

Platform Additions

Cooling

Temperature

Speed

Advanced

Ooze

Other

Special

GCode

Notes

☒ Enable Cooling Fans

Cooling

Minimal Layer Print Time

15.0

sec

☐ Wait for cooling to reach minimal layer time☒ Slow Down Printing Speed

Minimal Printing Speed

10.0

mm/s

☐ Avoid slowing down outer shell speed☒ Increase Fan Speed

Maximum Fan Speed

40

%

☐ Blip fan speed to 100% when starting from low speed

Low Fan Speed Threshold

30

%

Blip Fan Speed Pause Duration

500

msec

Other

☐ Wait for movement finished before changing fan speed

Fan Control

External Cooling

Layer

1

Fan Speed

0

%

Add Fan Point

Remove Fan Point

Layer

Fan Speed

2

25

4

60

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

Type here to search (Ctrl + F)

Quality Layer Extruder Infill Solid Fill Support Platform Additions Cooling **Temperature** Speed Advanced Ooze Other Special GCode Notes

Temperature

Heated Bed Temperature 50 °C

Primary Extruder 190 °C

☐ Use Temperature Control List

Heated Bed

Primary Extruder

Layer

1

Temperature

40

°C

Add Temperature

Remove Temperature

Layer

Temperature

☐ Cool Down Inactive Extruder☒ Move to Park Position

Park Position X

30.00

mm

Park Position Y

122.50

mm

Inactive Cooling Temperature (Left)

180

°C

Inactive Cooling Temperature (Right)

180

°C

☐ Heat up Inactive Extruder in Advance

Heat up Ahead of Time

40.0

sec

Inactive Heating Temperature (Left)

200

°C

Inactive Heating Temperature (Right)

200

°C

☐ Cool Down before Extruder Switch

Decrease Raft Surface and Model First Layer Temp.

0

°C

☐ Bottom Surface Temperature

Bottom Surface Temperature

200

Deg

Bottom Surface Temperature Area Threshold

200.0

mm²

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

Type here to search (Ctrl + F)

Quality Layer Extruder Infill Solid Fill Support Platform Additions Cooling Temperature Speed Advanced Ooze Other Special GCode Notes

Speed

Default Printing Speed	40.0	mm/s
Inner Shell Speed	40.0	mm/s
Outer Shell Speed	35.0	mm/s
Infill Speed	60.0	mm/s
Base Solid Fill Speed	60.0	mm/s
Solid Fill Speed	60.0	mm/s
Top Surface Solid Fill Speed	30.0	mm/s
Bottom Surface Solid Fill Speed	60.0	mm/s
Thin Wall Speed	50.0	mm/s
Gap Filling Speed	60.0	mm/s
Bridging Speed	60.0	mm/s
Inner Bridging Speed	60.0	mm/s
Bridging Shells Speed	30.0	mm/s

Support

Support Speed	50.0	mm/s
Solid Base Layers Speed	50.0	mm/s
Dense Support Speed	50.0	mm/s

Overhang Shells Speed

50.0 mm/s

Overhang Shells Speed List

Angle 30 Deg

Speed 30.0 mm/s

Add

Remove

Angle	Speed
-------	-------

First Layer Speed

40.0 mm/s

☐ First Layer Solid Fill Speed

40 mm/s

Slow Down First Few Layers

3

X/Y Axis Movement Speed

65.0 mm/s

Z Axis Movement Speed

5.0 mm/s

Raft X/Y Axis Movement Speed

65.0 mm/s

Maximum Volumetric Speed

0.00 mm³/s☐ Smoothing Volumetric Speed

Smoothing Volumetric Speed Threshold

1.00 mm³/s

Smoothing Volumetric Speed Segment Length

3.00 mm

Smoothing Volumetric Speed Travel Length Threshold

5.00 mm



Restore

Save As

Cancel

OK

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

🔍 Type here to search (Ctrl + F)

Quality

Layer

Extruder

Infill

Solid Fill

Support

Platform Additions

Cooling

Temperature

Speed

Advanced

Ooze

Other

Special

GCode

Notes

☐ AccelerationPrinting Acceleration 500.00 mm/s²Inner Shell Acceleration 500.00 mm/s²Outer Shell Acceleration 500.00 mm/s²Infill Acceleration 500.00 mm/s²Base Solid Fill Acceleration 500.00 mm/s²Solid Fill Acceleration 500.00 mm/s²Top Surface Solid Fill Acceleration 500.00 mm/s²Bottom Surface Solid Fill Acceleration 500.00 mm/s²Support Acceleration 500.00 mm/s²☐ First Layer Acceleration 500.00 mm/s²Travel Acceleration 500.00 mm/s²Travel Short Distance Acceleration 0.00 mm/s²

Primary Extruder

☐ Pressure Advance (Left Extruder)

Fixed PA

0.0000

☐ Jerk

Printing Jerk 5.00 mm/s

Inner Shell Jerk 5.00 mm/s

Outer Shell Jerk 5.00 mm/s

Infill Jerk 5.00 mm/s

Base Solid Fill Jerk 5.00 mm/s

Solid Fill Jerk 5.00 mm/s

Top Surface Solid Fill Jerk 5.00 mm/s

Bottom Surface Solid Fill Jerk 5.00 mm/s

Support Jerk 5.00 mm/s

☐ First Layer Jerk 5.00 mm/s

Travel Jerk 5.00 mm/s

☐ Jerk Settings support for Delta printers☐ Override Material Settings

Primary Material Flowrate 95.0 %

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

Type here to search (Ctrl + F)

Quality

Layer

Extruder

Infill

Solid Fill

Support

Platform Additions

Cooling

Temperature

Speed

Advanced

Ooze

Other

Special

GCode

Notes

Other

☒ Force Retraction On Layer Change☒ Force Retraction Before Traveling to Outer Shell☐ Avoid Retraction at Start☐ Avoid Retraction Inside Models☐ Enable Retraction at Bottom and Top of Models

Bottom Layers

1

Top Layers

2

☒ Avoid Traveling Through Holes☐ Enable Maximum Travel Path Length

Maximum Travel Path Length

200

%

Force Retraction if Travel Length Exceed

0.00

mm

☐ Stop printing Wipe Wall and Wipe Tower☒ Cool down inactive extruder if only one extruder is used in remaining task

Wipe Wall and Wipe Tower Brim Width

2.0

mm

☒ Wipe Wall

Wipe Wall Mode

Interlaced

Wipe Wall Offset

2.00

mm

Wipe Wall Angle

30

Deg

Wipe Wall Loop Lines

1

Wipe Wall Type

WaterFall

Wipe Wall Speed

50.0

mm/s

☐ Force printing Wipe Wall for single extruder prints

Restore

Save As

Cancel

OK

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile

Type here to search (Ctrl + F)

Quality

Layer

Extruder

Infill

Solid Fill

Support

Platform Additions

Cooling

Temperature

Speed

Advanced

Ooze

Other

Special

GCode

Notes

☐ Merge Open Segments of Model Parts☐ Merge Internal Overlapping Parts☐ Print Non-Manifold Edges☐ Check Thin Wall (Single Extrusion Width)

Minimal Extrusion Width Percentage

25 %

Maximum Extrusion Width Percentage

200 %

☒ Fill Gaps in Shells☐ Fill Gaps Only at Top and Bottom Surfaces

Minimal Single Extrusion Width Percentage

33 %

Maximum Single Extrusion Width Percentage

200 %

☐ Single Extrusion Filling Compensation

66 %

Gap Filling Minimal Length

0.00 mm

☐ Overhang Shells Detection

Overhang Shells Angle

30 Deg

Overhang Shells Flowrate

100.0 %

☐ Enable Overhang Shells Fan Speed

100 %

Global Offset

X

0.00

Y

0.00

Z

0.00

Pause at Height

Height

5.000

mm

Add

Remove

The height property does not include raft.

☒ Enable Bridging Detection

Bridging Extrusion Width Percentage

100 %

☐ Detect inner bridging fills above sparse infill

Inner Bridging Extrusion Width Percentage

100 %

☐ Enable Bridging Fan Speed

100 %

☐ Enable Fixed Bridging Angle

0 Deg

Minimal Allowed Bridging Area

20.00 mm²

Bridging Flowrate

100.0 %

Inner Bridging Flowrate

100.0 %

Maximum Supported Area Percentage

50 %

☐ Apply Bridging Settings to Shells

Bridging Shells Flowrate

100.0 %

☐ Small Features

Small Features Diameter

10.00 mm

Small Features Holes Diameter

7.00 mm

Small Features Speed Multiplier

50 %

☐ Small Features Infill Density

100 %



Restore

Save As

Cancel

OK

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile



Quality Layer Extruder Infill Solid Fill Support Platform A

☒ Lateral Surface Texture☒ Texture Lighter Color Up☐ Texture Color Normalized

Texture XY Offset

1.00

mm

Texture Resolution

0.20

mm

☐ Texture Outside Only☐ Interlocking Structure

Interlocking Cell Width

0.80

mm

Interlocking Cell Direction

22.5

Deg

Interlocking Cell Layers

2

Interlocking Depth

2

Interlocking Boundary Distance

2



Layer Height

First Layer Height

First Layer Extrusion Width Percentage

Enable First Layer Solid Fill Extrusion Width Percentage

First Layer Solid Fill Extrusion Width Percentage

Outer Shell Extrusion Width Percentage

Inner Shell Extrusion Width Percentage

Infill Extrusion Width Percentage

Base Solid Fill Extrusion Width Percentage

Solid Fill Extrusion Width Percentage

Top Surface Solid Fill Extrusion Width Percentage

Bottom Surface Solid Fill Extrusion Width Percentage

Support Extrusion Width Percentage

First Layer Flowrate

Enable First Layer Solid Fill Flowrate

e Notes



Restore

Save As

Cancel

OK

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile



Quality Layer Extruder Infill Solid Fill Support Platform A

☒ Lateral Surface Texture☒ Texture Lighter Color Up☐ Texture Color Normalized

Texture XY Offset

1.00

mm

Texture Resolution

0.20

mm

☐ Texture Outside Only☐ Interlocking Structure

Interlocking Cell Width

0.80

mm

Interlocking Cell Direction

22.5

Deg

Interlocking Cell Layers

2

Interlocking Depth

2

Interlocking Boundary Distance

2



Layer Height

First Layer Height

First Layer Extrusion Width Percentage

Enable First Layer Solid Fill Extrusion Width Percentage

First Layer Solid Fill Extrusion Width Percentage

Outer Shell Extrusion Width Percentage

Inner Shell Extrusion Width Percentage

Infill Extrusion Width Percentage

Base Solid Fill Extrusion Width Percentage

Solid Fill Extrusion Width Percentage

Top Surface Solid Fill Extrusion Width Percentage

Bottom Surface Solid Fill Extrusion Width Percentage

Support Extrusion Width Percentage

First Layer Flowrate

Enable First Layer Solid Fill Flowrate

e Notes



Restore

Save As

Cancel

OK

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile



Quality

Layer

Extruder

Infill

Solid Fill

Support

Platform Additions

Cooling

Temperature

Speed

Advanced

Ooze

Other

Special

GCode

Notes

Start GCode

End GCode

Extruder Switch GCode

Layer Change GCode

Retraction GCode

Repetition GCode

Post-process

End Gcode

```
M104 S0 ;extruder heater off  
M140 S0 ;heated bed heater off (if you have it)  
G91 ;relative positionion  
G1 E-1 F300 ;retract the filament a bit before lifting the nozzle, to release some of the pressure  
G1 Z+10 E-5 F9000 ;move Z up and retract filament even more  
M84 ;steppers off
```

Built-In Placeholders

(Double click item to add to gcode)

▼ Slice Settings

{travel_xy_speed}

{layer_default_speed}

{retraction_speed1}

{temperature_extruder1}

{temperature_extruder2}

{temperature_heatbed}

{extruder_switch_retraction_amount1}

► Other Variables

Add More

Remove Selected

☒ Turn off Fan Cooling in End GCode☒ Reset Global Flow Rate to 100% in End GCode☒ Turn off Nozzle Heating in End GCode

Traveling along Z axis after finishing printing models

5.00



mm



Restore

Save As

Cancel

OK

Template: Printer1_ANET_A8_...RPI3_SKR2_Ideamaker_Profile



Quality

Layer

Extruder

Infill

Solid Fill

Support

Platform Additions

Cooling

Temperature

Speed

Advanced

Ooze

Other

Special

GCode

Notes

Notes




Restore

Save As

Cancel

OK

Printer1_ANET_A8_Plus_RPI3_SKR2_Ideamaker_Current_Profile.bin




Printer1_ANET_A8_Plus_RPI3_SKR2_Ideamaker_Current_Profile
X axle 48,63mm instead of 50mm



Printer1_ANET_A8_Plus_RPI3_SKR2_Ideamaker_Current_Profile
Y axle 49,76mm instead of 50mm



Printer1_ANET_A8_Plus_RPI3_SKR2_Ideamaker_Current_Profile.bin
Z axle 50,21mm instead of 50mm



Printer1_ANET_A8_Plus_RPI3_SKR2_Ideamaker_Current_Profile.bin
Edge problem overflow

