## **Build firmware**



- git clone https://github.com/espruino/Espruino
- cd Espruino
- source scripts/provision.sh ESP32 (if error, try again)
- OSX: read https://esp-idf.readthedocs.io/en/v2.0/macossetup.html (if cannot execute binary file error occured)
- make clean && BOARD=ESP32 make
- Voila!

## Upload new firmware on your ESP



```
esp-idf/components/esptool py/esptool/esptool.py
--chip esp32
--port /dev/tty.SLAB USBtoUART
--baud 921600
--after hard reset write flash
-Z
--flash mode dio
--flash freq 40m
--flash size detect
0x1000 espruino 1v94.3369 esp32/bootloader.bin
0x8000 espruino 1v94.3369 esp32/partitions espruino.bin
0x10000 espruino esp32.bin
```