Visit Report



To : GUOE, JIAJ

JIAJ

Cc : FNM, CAAG, GUOS, YAGK, LIAW, GUOC, ZHAI, XUEA, LINR, FUJT

Date of visit: 11 Jul. 2023 Date of report: 14 Jul. 2023

From : Lide

Participants : Customer : Mr. Xie (P.E),

Mr. Zhou (Processing supervisor)

EMS : J. Jin, E. Guo

OEM : Hikvision Sales responsible : GUOE Distributor : No

Location : Hangzhou

Application : Anticorrosion camera

Segment Code : 150

Project number : 150-220729-1


Material : Grivory FE11898 (GVX-5HL V1)

USP : Tailor-made material

(UL94 V1, UV resistance)

Potential : 100 t/a SOP : Running







1. Target of visit

Attend the meeting to discuss the solutions for solving/improving the yellowish issue as request by customer

2. Summary

- Meeting minutes
 - Dry-blened solution can't achieve stable surface quality with exist processing condition
 - Customer agree to trial FE11898 immediately, and convince Hikvision approve it with testing data
- DOE is not going smoothly due to yellowish issue on the newly equipeed anti-corrosion screw injection machine
- Customer will re-do the DOE with FE11898 on the other IMM when it is available
- Obtain the DOE result by 20th.Jul

3. Details

 Customer mentioned the yellowish situation getting more severe with dry blend (GVX-5HL: XE11119 = 1:1) solution on the No.39 injection moulding machine which newly equipeed anti-corrosion screw

- Base on above situation, customer request EMS to attend the meeting on site to discuss the solutions for solving/ improving the yellowish.
- Meeting minutes:
 - Dry-blened solution can't achieve stable surface quality due to salty loss during dry blend action
 - Don't trial dry blend material this time
 - Lide agree to do DOE with FE11898 (Lot. 6012734/01 higher notched impact strength) immediately on No. 39 injection moulding machine (newly epuiped anticorrsion screw), and will convince Hikvision conduct mass production with FE11898 if achieving positive DOE result
- DOE trial result:
 - The yellowish issue was also severe: processing adjustment (melt temperature, dosing speed, dosing delay,back pressure, enhenced veting) didn't work
- Then decide to trial the FE11898 grey (Lot.6013045/01 lower notched impact strength), which been verified on No.28 injection moulding machine w/o any yellowish issue (trial supported on 29th.Jun), unfortunatly, this batch also has severe yellowish
- Base on above trial results, the screw parameters may has significant influence on the yellowish defects

	No. 39 IMM	No. 28 IMM
Machine brand	Yizumi	Yizumi
Machine size	260 ton	260
Screw diameter	60mm	60mm
Screw compression ratio	2.55	2.4
Length/ diameter	20.5:1	22:1
Special treatment	Anti-corrosion	None
Trial result	Severe yellowish	None yellowish

 Customer will re-do the DOE with FE11898 (Lot. 6012734/01) on No. 28 IMM when it is available

Part & test requirement

- Salt mist resistance (GB/T 2423.18; IEC 60068-2-52) (Corrosion-proof)
- Corrosion gases resistance (GB/T 2423.51; IEC 60068-2-60) (Corrosion-proof)
- Impact resistance (GB 3836.1-2010/ IEC 60079-0-2007) (Explosion-proof)
- Vibration test@ 0.7g acceleration speed (0.024%)
- 0.8m steel ball drop test w/o breakage (Not specified testing standard, just as products quality control)

4. Actions

No.	Action	Resp.	Due date
1	Obatin DOE testing result	JIAJ	20 Jul. 2023

5. Attachments

Yellowish overview



Best regards,

Jason Jin

EMS	Process data injection	moulding TCS	
Customer	Name	Lide	
	Location	Hangzhou	
	Date	11.07.2023	
	Name of contact person	Tianchuan Xie	
Part	Name	Housing	
	Application	Anti-corrsion Camera	
	Project- / TI-Number	150-220729-1 / 2022-0516S	
Material	Name	Grivory FE11898 (GVX-5HL V1)	
	Colour	Grey	
IMM	Model name	Lide	
	Clamping force [kN]	2600	
	Screw diameter [mm]	60	
	Nozzle (type/diameter) [mm]	Open (3.5mm)	
Tool	Description of tool	2 plates	
	Number of cavities	1	
	Sprue/runner (type/dim.)	Sprue gating	
Gate (number/type/dimensions)		1 (8mm)	
	Insulating plates (yes/no)	no	
Dryer	Model name	no	
Type of dryer		no	
	Dew point [°C]		
Comments			

 Name
 Jason Jin

 Date
 11.07.2023

Trial #			Comments
Material		Grivory GVX-5HL V1	Comments
Colour		Grey C22316.1	
Lot. Nr.		6013045/01	
Barrel Temperatures		0013043/01	
Throat	[°C]		
Zone 1			
	[°C]		
Zone 2	[°C]	0.15	
Zone 3	[°C]	245	
Zone 4	[°C]	275	
Zone 5	[°C]	280	Adjustment: 250-285°C
Zone 6	[°C]	285	
Nozzle	[°C]	280	
Hot Runner			
Manifold	[°C]		
Nozzle 1	[°C]		
Nozzle 2	[°C]		
Nozzle 3	[°C]		
Nozzle 4	[°C]		
Melt Temp. measured	[°C]	287	
Tool Temperature	r -1		
Nozzle Side (NS)	[°C]	125	
Measured	[°C]	122	
Ejector Side (ES)	[°C]	95	
Measured	[°C]	115	
Slides		113	
	[°C]		
Measured	[°C]		
Core	[°C]		
Measured	[°C]		
Injection Phase			
Velocity 1 v1/s1	[%]/[mm]	35/115	
Velocity 2 v2/s2	[%]/[mm]	65/20	
Velocity 3 v3/s3	[%]/[mm]	20/18	
Max. allowed Inj. pressure	MPa	170	
Actual injection time	[s]	2.9	
Max. Injection pressure	[MPa]	143	
Hold on pressure phase			
Hold on pressure 1	[bar]/[s]	30/0.5	
Hold on pressure 2	[bar]/[s]	70/3	
Hold on pressure 3	[bar]/[s]	40/2	
Max. hold on speed	[mm/s]	20	
Wax. Hold off opecu	[11111/0]		
Switch Over			
Method	[position]	Position	
Value	[mm]	18	
Cushion		9	1
Dosing	[mm]	3	
	[mm]	105	
Metering stroke	[mm]	125	
Decompression	[mm]	5	
Screw dosing speed	[%]	60	
Back pressure	[kgf/cm ²]	6	Adjustment: 2-10bar
Dosing time	[s]	14	
Dosing delay	[s]	15	
Nozzle retraction	[mm]		
Cooling time	[s]	26	
Cycle time	[s]	68	
Part weight	[g]	450	
Pre-drying	[h at °C]		
Moisture content	[%]		Desiccant dryer is not ready, trialed with
Remarks			newly opened material. Moisture content
			is 0.05%
			1
		I.	I .