

## Marlin 2.0.x Firmware Changes



In Platformio.ini file  
change: `default_envs = BIGTREETECH_GTR_V1_0`

In Configuration.h file change:

```
#define SERIAL_PORT -1
#define SERIAL_PORT_2 3
#define MOTHERBOARD
MOTHERBOARD BOARD_BTT_GTR_V1_0
```

Note: Serial Port definitions in Marlin 2.0.x for GTR V1.0 Board:  
-1: USB Port; 3: TFT Port; 6: WIFI

0 - M1; MS1	0 - M0; MS0
1 - M2; MS2 OR 1 - M1; MS1	1 - M1; MS1
2 - M3; MS3	2 - M2; MS2



\*1 THE CORRECTED PIN VALUE. THE CORRECT PIN VALUE CAME FROM BTT's GTR V1.0 SCHEMATIC DIAGRAM!

