






PA6

DET PC4

bout any of the and board's schematic

ote: If you are unsure nformation provided on this PIN Diagram, please ask for help from the 3D rinter community, check the Processor's data she



**SPI1 Header** 

/ GND

**MOTOR UART** 

RX

EN STEP DIR

XM PB14 PB13 PB12

YM PB11 PB10 PB2

ZM PB1 PB0 PC5

EM PD1 PB3 PB4

**STALLGUARD** 

(Sensor-less Homing)

PC0

PC1

X-STOP

Y-STOP

PC2 Z-STOP

PC15 E0-STOP

**DIAG PIN ENDSTOP** 

SW\_USB

MCU Powered

by USB-C Port

**MCU** Powered

by POWER IN