	Energético				Mando central									Interfaz			
	Cr1	Cr2	Cr3	Cr4	Cr5	Cr6	Cr7	Cr8	Cr9	Cr10	Cr11	Cr12	Cr13	Cr14	Cr15	Cr16	Cr17
Cr1	1	2	2	1/3	1/2	2	1/3	1/2	1/2	1	1/2	1/2	1/3	1/3	1/3	1	3
Cr2	1/2	1	2	1/3	1/3	2	1/3	1/3	1/3	1/2	1/2	1/3	1/4	1/4	1/4	1/2	3
Cr3	1/2	1/2	1	1/4	1/2	1	1/3	1/3	1/3	1/2	1/2	1/3	1/4	1/3	1/3	1/2	2
Cr4	3	3	4	1	2	3	1	1/2	1	3	2	2	1	1/2	1/2	1	3
Cr5	2	3	2	1/2	1	3	1/3	1/3	1	1/2	1/2	1/3	1/3	1/3	1/3	1	3
Cr6	1/2	1/2	1	1/3	1/3	1	1/4	1/4	1/3	1/4	1/3	1/4	1/3	1/4	1/4	1/2	1
Cr7	3	3	3	1	3	4	1	1/3	1 /2	1	1	1	1/3	1/3	1/3	1	3
Cr8	2 2	3	3 3	2 1	3	4	3 1	2	1/2	$\frac{1}{1/2}$	2 2	$\frac{1}{1/2}$	1/2 $1/3$	1/2 $1/2$	1/2 $1/3$	1 2	3 4
Cr10	1	2	2	1/3	2	3 4	1	1	2	1/2	2	1/2 $1/2$	1/3 $1/2$	1/2 $1/2$	1/3 $1/2$	1	3
Cr11	2	2	2	1/2	2	3	1	1/2	1/2	1/2	1	1/3	1/3	1/3	1/3	1/2	2
Cr12	2	3	3	1/2	3	4	1	1	2	2	3	1	1/3	1/3	1/3	1/2	3
Cr13	3	4	4	1	3	3	3	2	3	2	3	3	1	3	4	1	4
Cr14	3	4	3	2	3	4	3	2	2	2	3	3	1/3	1	1	3	4
Cr15	3	4	3	2	3	4	3	2	3	2	3	3	1/4	1	1	3	4
Cr16	1	2	2	1	1	2	1	1	1/2	1	2	2	1	1/3	1/3	1	1/2
Cr17	1/3	1/3	1/2	1/3	1/3	1	1/3	1/3	1/4	1/3	1/2	1/3	1/4	1/4	1/4	2	1
Cr18	1/2	1/2	1	1/3	1/3	1	1/3	1/3	1/3	1/3	1/2	1/3	1/3	1/3	1/3	1/2	2
Cr19	1/3	1/2	1	1/4	1/3	1/2	1/3	1/4	1/3	1/3	1/3	1/3	1/4	1/3	1/2	1/3	1
Cr20	4	4	5	1	4	4	3	2	3	3	3	3	2	4	3	4	5
Cr21	4	4	4	2	4	4	3	3	3	2	3	3	3	4	4	4	4
Cr22	3	4	4	2	4	4	3	3	3	2	3	3	2	3	3	4	4
Cr23	3	3	4	1	3	4	3	2	3	2	3	2	3	2	2	3	3
Cr24	3	3	3	1	3	4	3	2	3	2	3	2	3	2	2	3	3
Cr25	3	4	4	1	3	4	3	2	3	2	2	2	3	3	3	3	4
Cr26	4	4	4	2	4	4	3	3	3	2	3	3	3	4	4	4	4
Cr27	1/2	1/2	1	1/3	1/3	1	1/3	1/3	3	1/3	1/2	1/3	1/3	1/2	1/2	1/2	2
Cr28	1/3	1/2	1	1/4	1/3 4	$\frac{1}{2}$	1/3 3	$\frac{1}{4}$	3 3	1/3	1/3 3	$\frac{1}{3}$	$\frac{1}{4}$	1/3	$\frac{1}{2}$	1/3	1
Cr29 Cr30	4	4	5 4	1 2	4	4	э 3	3	э 3	3 2	3	3	3	4	3 4	4	5 4
Cr31	3	4	4	2	4	4	3	3	3	2	3	3	2	3	3	4	4
Cr32	3	3	4	1	3	4	3	2	3	2	3	2	3	2	2	3	3
Cr33	4	4	3	2	4	4	3	3	3	3	3	3	1/3	4	4	3	3
Cr34	3	3	4	1	3	4	3	2	3	2	3	2	3	2	2	3	3
Cr35	3	4	4	1	3	4	3	2	3	2	2	2	3	3	3	3	4
Cr36	4	4	4	2	4	4	3	3	3	2	3	3	3	4	4	4	4
Cr37	4	4	5	3	3	5	4	3	3	2	3	3	4	3	4	3	4
Cr38	4	5	5	2	3	5	4	3	3	2	3	2	1	4	4	2	4
Cr39	3	4	3	1/3	3	1	1/3	1/3	3	1/4	1	3	1/3	3	3	1/4	4
Cr40	1/2	1	3	1/2	1	3	1/2	1/3	1/2	1/3	1/2	1/3	1/4	1/3	1/3	1/3	1
Cr41	1	1	2	1/2	1/2	2	1/2	1/3	1/2	1/3	1/3	1/3	1/3	1/2	1/3	1/2	2
Cr42	4	4	4	1	3	4	3	1	2	2	2	2	3	3	3	4	4
Cr43	1/2	1	1	1/3	1/2	2	1/3	1/3	1/2	1/3	1/3	1/3	1/3	1/3	1/3	1/2	2
Cr44	3	4	4	1/2	3	3	3	4	3	3	4	3	2	3	4	2	5
Cr45	1	3	2	1/3	2	3	1/2	3	2	1/3	3	3	1/3	3	3	1/3	3
Cr46	1/3	3	3	1/3	1/3	3	1/3	1/3	1/3	1/3	1	1	1/3	2	1	1/4	4
Cr47	3	1	1	1/3	3	4	4	3	1	1/2	3	3 2	1/3	3	4 2	1/3	5
Cr48 Cr49	$\frac{1/2}{5}$	1 5	$\frac{1}{2}$	1/3 1	1 4	3 5	2	3 2	$\frac{1}{2}$	$\frac{1}{3}$	2 3	3	$\frac{1}{3}$	3	4	1/3 5	3 5
Cr49	2	э 3	3	3	2	5 5	э 3	2	2	3 2	3	3	3 2	3	3	э 3	4
Cr50	5	5 5	5 5	3	4	5 5	2	3	3	2	3	2	2	4	3	3 4	5
Cr52	5	5	5	2	4	5	2	1	2	3	3	3	1/3	3	3	3	4
Cr53	4	5	5	3	4	5	1	2	3	3	3	3	1/3	2	3	4	4
Cr54	1/2	3	3	1/2	3	3	2	3	3	2	3	3	1/3	3	3	2	5
1	ı -, -	~	~	-, -	-	~	_	~	~	_	~	~	-, -	ı ~	~	_	~