	Estructural										Generales							
	Cr37	Cr38	Cr39	Cr40	Cr41	Cr42	Cr43	Cr44	Cr45	Cr46	Cr47	Cr48	Cr49	Cr50	Cr51	Cr52	Cr53	Cr54
Cr1	1/4	1/4	1/3	2	1	1/4	2	1/3	1	3	1/3	2	1/5	1/2	1/5	1/5	1/4	2
Cr2	1/4	1/5	1/4	1	1	1/4	1	1/4	1/3	1/3	1	1	1/5	1/3	1/5	1/5	1/5	1/3
Cr3	1/5	1/5	1/3	1/3	1/2	1/4	1	1/4	1/2	1/3	1	2	1/5	1/3	1/5	1/5	1/5	1/3
Cr4	1/3	1/2	3	2	2	1	3	2	3	3	3	3	1	1/3	1/3	1/2	1/3	2
Cr5	1/3	1/3	1/3	1	2	1/3	2	1/3	1/2	3	1/3	1	1/4	1/2	1/4	1/4	1/4	1/3
Cr6	1/5	1/5	1	1/3	1/2	1/4	1/2	1/3	1/3	1/3	1/4	1/3	1/5	1/5	1/5	1/5	1/5	1/3
Cr7	1/4	1/4 $1/3$	3 3	2 3	2	1/3 1	3 3	1/3	2 1/2	3 3	1/4	1/2	1/3 1/2	1/3 $1/2$	1/2 $1/3$	1/2 1	$\frac{1}{1/2}$	1/2
Cr9	1/3	1/3	3 1/3	2	2	$\frac{1}{1/2}$	2	1/4 $1/3$	1/3 $1/2$	3	1/3 1	$\frac{1}{3}$	1/4	1/2 $1/2$	1/3	1/2	1/3	$\frac{1/3}{1/3}$
Cr10	1/3	1/3	4	3	3	1/2 $1/2$	3	1/3	3	3	2	3	1/3	1/2 $1/2$	1/3	1/3	1/3	1/2
Cr11	1/3	1/3	1	2	3	1/2	3	1/4	1/3	1	1/3	1/2	1/3	1/3	1/3	1/3	1/3	1/3
Cr12	1/3	1/2	1/3	3	3	1/2	3	1/3	1/3	1	1/3	1/2	1/3	1/3	1/2	1/3	1/3	1/3
Cr13	1/4	1	3	4	3	1/3	3	1/2	3	3	3	3	1/3	1/2	1/2	3	3	3
Cr14	1/3	1/4	1/3	3	2	1/3	3	1/3	1/3	1/2	1/3	1/2	1/3	1/3	1/4	1/3	1/2	1/3
Cr15	1/4	1/4	1/3	3	3	1/3	3	1/4	1/3	1	1/4	1/2	1/4	1/3	1/3	1/3	1/3	1/3
Cr16	1/3	1/2	4	3	2	1/4	2	1/2	3	4	3	3	1/5	1/3	1/4	1/3	1/4	1/2
Cr17	1/4	1/4	1/4	1	1/2	1/4	1/2	1/5	1/3	1/4	1/5	1/3	1/5	1/4	1/5	1/4	1/4	1/5
Cr18	1/3	1/4	1/3	1/2	1/2	1/4	1/3	1/4	1/3	3	1/3	1	1/5	1/3	1/4	1/4	1/5	1/5
Cr19	1/4	1/5	1/3	1/3	1/2	1/3	1	1/3	1	3	1/3	1	1/5	1/4	1/5	1/5	1/4	1/5
Cr20	1/2	1	4	3	2	2	3	3	3	5	4	3	1/4	1/2	1/4	1/4	1/3	1/3
Cr21	1/2	1/3	3	3	3	2	3	1	3	4	3	4	1/4	1/4	1/4	1/3	1/2	1/2
Cr22	1/2	1/3	3	2	3	1/3	3	1/3	3	3	3	3	1/4	1/2	1/3	1/4	1/3	1
Cr23	1/3	1/4	2	2	2	1/2	2	1/3	1/2	2	1/3	1/3	1/5	1/3	1/4	1/4	1/3	1/2
Cr24	1/4	1/4	2	2	1	1/2	1	1/3	1/2	2	1/3	1/3	1/5	1/4	1/5	1/5	1/4	1/2
Cr25	1 1/2	1/3 $1/4$	3 3	$\frac{1}{2}$	$\frac{1}{3}$	1/3 $1/2$	3 3	1 1	3 4	4	3	3	1/4	1/3	1/5	1/3	1/3 $1/3$	$\frac{1}{1/2}$
Cr26 Cr27	1/3	1/4	3 1/3	3	1/3	$\frac{1/2}{1/4}$	3 1	1/4	1/3	3	3 1/3	1	1/4	1/3 $1/4$	1/4 $1/5$	1/3 $1/4$	1/3	1/5
Cr28	1/3	1/5	1/3	1/3	1/3	1/4	1	1/3	1/3	3	1/3	1	1/5	1/4	1/5	1/4	1/3	1/5
Cr29	2	2	4	4	3	1	3	3	3	5	4	3	1/3	1/3	1/3	2	3	1/3
Cr30	1/2	1/3	3	3	3	1/3	3	1	3	4	3	4	1/3	1/2	1/5	2	1	1/2
Cr31	1/2	1/3	3	3	3	1/2	3	1/3	3	3	3	3	1/3	1/2	1/5	1/3	3	1
Cr32	1/3	1/4	2	3	1	1/3	1	1/3	1/2	2	1/3	1/3	1/5	1/5	1/5	1/3	1	1/2
Cr33	1	1/3	1/3	3	4	1/3	3	3	1/3	1	1/3	1/3	1/3	1/3	1/4	1/2	3	1/3
Cr34	1/3	1/4	2	3	1	1/3	1	1/3	1/2	2	1/3	1/3	1/5	1/4	1/5	1/3	1	1/2
Cr35	1	1/3	3	3	3	1/3	3	1	3	4	3	3	1/3	1/4	1/3	2	3	1
Cr36	1/3	1/3	3	3	3	1/2	3	1	4	4	3	4	1/3	1/4	1/4	2	3	1/2
Cr37	1	1/3	4	3	4	1/3	3	2	3	3	3	3	1/5	1/3	1/5	1/5	1/5	2
Cr38	3	1	4	3	5	1	4	2	4	4	3	4	1/3	1	1/3	3	3	1
Cr39	1/4	1/4	1	1	1/3	1/3	2	1/3	1	4	1	4	1/3	1/2	1/4	1/3	2	1/5
Cr40	1/3	1/3	1	1	1/3	1/3	3	1/3	1/2	1/3	1/2	1	1/5	1/5	1/5	1/3	1	1/3
Cr41 Cr42	1/4	1/5 1	3 3	3	4	1/4	2 4	$\frac{1}{2}$	$\frac{1}{2}$	2 3	2 4	2 3	1/5	1/3	1/5	1/5	1 3	$\frac{1/2}{1}$
Cr42	1/3	1/4	$\frac{3}{1/2}$	3 1/3	1/2	1/4	1	3 1/3	3 1	3 1	1	3	1/4 1/5	1/3 $1/5$	1/4 $1/5$	1/3 $1/3$	3 1/3	1/3
Cr44	1/2	1/2	3	3	2	1/3	3	1	3	3	3	3	1/3	1/3 $1/2$	1	3	1	3
Cr45	1/3	1/4	1	2	2	1/3	1	1/3	1	3	3	3	1/3	1	1/3	2	3	2
Cr46	1/3	1/4	1/4	3	1/2	1/3	1	1/3	1/3	1	1/3	1/3	1/4	1/4	1/5	1/4	1/3	3
Cr47	1/3	1/3	1	2	1/2	1/4	1	1/3	1/3	3	1	1	1/4	1/3	1/3	2	1/3	1
Cr48	1/3	1/4	1/4	1	1/2	1/3	1/3	1/3	1/3	3	1	1	1/4	1/3	1/5	1/5	3	1/3
Cr49	5	3	3	5	5	4	5	3	3	4	4	4	1	3	1	2	3	1/2
Cr50	3	1	2	5	3	3	5	2	1	4	3	3	1/3	1	1/4	1/3	1/3	1
Cr51	5	3	4	5	5	4	5	1	3	5	3	5	1	4	1	3	3	1/2
Cr52	5	1/3	3	3	5	3	3	1/3	1/2	4	1/2	5	1/2	3	1/3	1	5	1
Cr53	5	1/3	1/2	1	1	1/3	3	1	1/3	3	3	1/3	1/3	3	1/3	1/5	1	1/3
Cr54	1/2	1	5	3	2	1	3	1/3	1/2	1/3	1	3	2	1	2	1	3	1