User Manual

Table of Content:

STM32 motor control SDK overview	
Getting Started with Motor Control SDK	
Motor Profiler Application Note	
► Motor Control Firmware architecture	
Introduction to the PMSM FOC drive	
Permanent Magnet Motors structure	
PMSM fundamental equations	
PMSM maximum torque per ampere (MTPA) control	
Feed-forward current regulation	
Flux-weakening control	
PID regulator theoretical background	
A priori determination of flux and torque current PI gains	
Space vector PWM implementation	
Overmodulation	
Discontinuous PWM	
Reference frame transformations	
Circle limitation	
Current sampling	
Current sampling in three-shunt topology using two A/D converters	
Current sampling in three-shunt topology using one A/D converter	
HSO current and voltage sampling in three-shunt topology	
► Current sampling in single-shunt topology	
Single shunt with phase shift current sensing overview	
Current sampling in isolated current sensor topology	
Current sensing and protection using embedded OpAmps and Comparators	
Rotor speed & position feedback	
► Speed & position feedback sensorless algorithms	
Hall sensor feedback processing	
Quadrature Encoder sensor feedback processing	
Measurement Units used by the firmware	
Six-step Firmware Algorithm	
Electrical angle estimation compensation	
CPU load measurement feature	
MISRA compliance	
Position Control	
MC State Machine, Commands & Faults	
FreeRTOS in a Motor Control application	

► Motor Control Protocol Suite	
Open Loop Description and Usage	
► Firmware errors	
Motor Control features	
Terms and abbreviations	
Missing document notice	
Deprecated List	

