
Line -05 Map



STATIONS

- 1. Colorant Pouch Loader
- 2. Shade coding and Pouch Formation
- 3. Bottom and Vertical Sealing
- 4. Eye Mark Sensing
- 5. Cutting & Pouch Opening
- 6. Filling
- 7. Top Sealing & Transfer to next conveyor
- 8. Developer Roll Loader and Pouch formation
- 9. Eye Mark Sensing & Bottom Sealing
- Pouch opening, Vertical Sealing & Bulk Filling
- 11. Cutting on crimp and top sealing
- **12.** Cutting and transfer on the colorant pouch
- 13. Pusher
- 14. Presence sensor
- 15. Leaflet Loading
- 16. Leaflet Dispensing
- 17. Leaflet Sensor
- 18. Outer flow wrap roll loader
- 19. Domino coding
- 20. Pouch Formation
- 21. Sealing & Cutting
- 22. Weighing Balance
- 23. Case Packer

ZERO DEFECT DETECTORS

- 1. Colorant Empty Pouch Detector
- 2. Developer Empty Pouch Detector
- 3. Leaflet Detector