

Stabilizer สำหรับผู้ป่วยรูมาตอยส์

จัดทำโดย

1. นายกันตพงศ์ เปรมโยธิน 65070502202

2. นายชุติพนธ์ ลิขิตปริญญา 65070502204

เสนอ

อาจารย์ ชนากานต์ แคล้วอ้อม

รายงานฉบับนี้เป็นส่วนหนึ่งของรายวิชา MCE 242 COMPUTER SYSTEMS AND INTERFACING ภาคเรียนที่ 2 ปีการศึกษา 2566 สาขาวิชาวิศวกรรมเมคคาทรอนิกส์ ภาควิชาวิศวกรรมอุตสาหการและเมคคาทรอนิกส์

คณะวิศวกรรมศาสตร์

มหาวิทยาลัยเทคโนโลยีพระจอมเกล้าธนบุรี

MCE242 - 2024 Project Report

ผู้จัดทำ: นายกันตพงศ์ เปรมโยธิน รหัส 65070502202 MCE

นายชุติพนธ์ ลิขิตปริญญา รหัส 65070502204 MCE

Project Name: Stabilizer สำหรับผู้ป่วยโรครูมาตอยส์

ที่มาและความสำคัญ

เนื่องจากผู้ป่วยโรคข้ออักเสบรูมาตอยส์นั้นมักจะมีอาการเจ็บบริเวณข้อต่อของนิ้วมือและทำให้มือไม่มีแรง หยิบจับสิ่งของหรือเมื่อหยิบแล้วอาจเกิดอาการสั่น ทางผู้จัดทำได้เล็งเห็นถึงปัญหานี้ จึงได้ออกแบบเครื่องมือ สำหรับผู้ที่มีอาการสั่นเพื่อให้สามารถจับซ้อนได้อย่างมั่นคง

วัตถุประสงค์

- 1. แก้ปัญหาอาการมือสั่นของผู้ป่วยโรครูมาตอยส์
- 2. ศึกษาการทำงานของ MPU6050 และ Stepper motor
- 3. ศึกษาการทำงานของระบบควบคุมแบบ PID
- 4. ศึกษาการควบคุมระบบ ด้วยโปรแกรม BLYNK

ขอบเขต

1. ทั้ง 3 แกนเอียงไม่เกิน 180 องศา

วัสดุและอุปกรณ์ที่ใช้ในการสร้าง Stabilizer

1.	ESP32s	1	ตัว
2.	Arduino UNO R3	1	ตัว
3.	Breadboard	1	บอร์ด
4.	MPU6050	1	ตัว
5.	Stepper Motor (28BYJ-48)	3	ตัว
6.	Step Down Voltage	1	ตัว
7.	9V Battery	1	ก้อน
8.	รางถ่าน 9V		
9.	สายไฟจัมป์เปอร์		
10. PLA (สำหรับ 3D Printing)			

ขั้นตอนการดำเนินงาน

1. ศึกษาการทำงานของ MPU6050 (Gyroscope module) และ Stepper Motor


```
Gymoles

I disclude "TRYGOS ANAIS, Notionappison."

I stirclude "PROGOS ANAIS, Notionappison."

I stirclude "TRYGOS ANAIS ANAI
```


2. ทดสอบการทำงานร่วมกันของ MPU6050 และ Stepper Motor โดยการสื่อสารผ่าน I2C Communication ซึ่งมี ESP32 เป็น MASTER และ Arduino UNO R3 กับ MPU6050 เป็น SLAVE




3. ออกแบบหน้า Interface ของโปรแกรม Blynk เพื่อใช้ในการตั้งค่าองศาของอุปกรณ์ Stabilizer




4. ออกแบบโครงสร้างของอุปกรณ์และลองประกอบด้วยโปรแกรม Autodesk Inventor Professional 2024



5. ปริ้นท์ชิ้นงานที่ออกแบบด้วยเครื่องปริ้นท์ 3 มิติ



6. ประกอบชิ้นงานทั้งหมดกับชิ้นงานที่ปริ้นท์มา



ESP32s (MASTER) & MPU6050 Code (SLAVE)

*หมายเหตุ โค้ดทั้งหมดสามารถดาวน์โหลด หรือดูได้จากลิงก์ตามนี้

https://github.com/Gaplnwzaza/MCE242-Project-Stabilizer

```
This MCE242 project was created by 65070502202 Kantapong Premyodin and 65070502204 Chutipon Likitparinya
      The project name is 3-Axis stabilizer with adjust value and PID
      NOTE: First we use esp32 to drive motor but esp32 cannot hold that much voltage so we have to use another board
      and that board is Arduino UNO R3 by I2C communication \ensuremath{^{*/}}
   [/* Denote the second contraction of the second contraction [/*]
   #include "I2Cdev.h'
   #include "MPU6050_6Axis_MotionApps20.h"
10
   13
   17
18
                         INCLUDE LIBRARY AND DEFINE BLYNK INFO
   #define BLYNK_TEMPLATE_ID "TMPL6zOYVoFza"
   #define BLYNK_TEMPLATE_NAME "Quickstart Template"
   #define BLYNK_AUTH_TOKEN "s2cs7kf0603Rcx9-3eNtWDw3zi-LvkDw"
   #define BLYNK PRINT Serial
24
   #include <SPI.h>
   #include <Ethernet.h>
25
   #include <WiFi.h>
   #include <WiFiClient.h>
   #include <BlynkSimpleEsp32.h>
   // Your WiFi credentials
// Set password to "" for open networks
char ssid[] = "GaplnwZaZa";
30
32
   char pass[] = "gaplnwzaza";
33
35
        Set to 2.4 Ghz wifi by your | wifi name - ssid | wifi password - pass
    DEFINE FOR I2C COMMUNICATION
    #define slaveAddress 0x08 //you have to assign an 8-bit address to Slave Arduino UNO R3
11
   byte dataArray[3] = { 0 , 0 , 0 }; //To transmit data to Slave using I2C the data type must be byte data for stable transmission
    18
49
   MPU6050 mpu;
50
   #define OUTPUT READABLE YAWPITCHROLL
   bool dmpReady = false;
52
   uint8 t mpuIntStatus;
   uint8_t devStatus;
53
54
   uint16_t packetSize;
   uint16_t fifoCount;
55
   uint8_t fifoBuffer[64];
56
   Ouaternion g:
57
   VectorInt16 aa:
58
   VectorInt16 aaReal:
59
   VectorInt16 aaWorld:
60
61
   VectorFloat gravity;
   float ypr[3] = { 0 , 0 , 0 };
62
   float ROW, PITCH, YAW;
63
   /*
                             DEFINE FOR MOTOR CONTROL PIN [][][][][][][][][][][][][][]
```

```
69
     // #define MOTORA_IN1 4 // Direction control pin +
     // #define MOTORA_IN2 2 // Direction control pin -
     // #define MOTORB EN 2 // PWM pin for controlling motor PITCH axis speed // #define MOTORB_IN1 0 // Direction control pin +
 73
     // #define MOTORB_IN2 4 // Direction control pin
     // #define MOTORC_EN 2 // PWM pin for controlling motor YAW axis speed
 74
     // #define MOTORC_IN1 0 // Direction control pin + // #define MOTORC_IN2 2 // Direction control pin -
 78
     79
 80
     unsigned long Present_time, Previous_time;
 81
     float Delta_time;
int Present_state, Next_state;
 82
 83
     float Present_error_ROW, Intergral_error_ROW, Devirative_error_ROW, Previous_error_ROW;
 85
     float Present error PITCH, Intergral error PITCH, Devirative error PITCH, Previous error PITCH;
     float Present_error_YAW, Intergral_error_YAW, Devirative_error_YAW, Previous_error_YAW;
     float out_PITCH;
     float out_YAW;
 92
 93
     float set_point_ROW = 0;
 94
     float set_point_PITCH = 0;
 95
     float set_point_YAW = 0;
 96
 97
 98
          For adjust the position when you don't want to connected with blynk slider object
 99
100
     */
101
102
     float Min_out = -128;
     float Max_out = 127;
103
104
     float kp = 12; //10
     float ki = 0.009;//0.008
105
     float kd = 90;//75
106
107
108
109
           For Optimize PID CONTROL
110
111
112
113
     void setup() {
114
     //Define for MPU and I2C communication
       Wire.begin();
115
       Wire.setClock(400000);
116
117
       Serial.begin(115200);
118
119
120
       mpu.initialize();
121
122
       devStatus = mpu.dmpInitialize();
123
       mpu.setXGyroOffset(220);
124
       mpu.setYGyroOffset(76);
125
       mpu.setZGyroOffset(-85);
126
       mpu.setZAccelOffset(1788);
127
128
       if (devStatus == 0) {
129
       mpu.CalibrateAccel(6);
130
131
         mpu.CalibrateGyro(6);
       mpu.PrintActiveOffsets();
132
```

```
133
         mpu.setDMPEnabled(true);
         mpuIntStatus = mpu.getIntStatus();
134
         packetSize = mpu.dmpGetFIFOPacketSize();
135
136
137
138 ✓ //Connected with blvnk
       Blynk.begin(BLYNK_AUTH_TOKEN, ssid, pass);
139
140
141 ✓ //Define OUTPUT for 3-axis motor pin
       // pinMode(MOTORA_EN, OUTPUT);
142
       // pinMode(MOTORA_IN1, OUTPUT);
143
       // pinMode(MOTORA_IN2, OUTPUT);
144
       // pinMode(MOTORB_EN, OUTPUT);
145
146
       // pinMode(MOTORB_IN1, OUTPUT);
147
       // pinMode(MOTORB_IN2, OUTPUT);
148
       // pinMode(MOTORC_EN, OUTPUT);
149
       // pinMode(MOTORC_IN1, OUTPUT);
150
       // pinMode(MOTORC_IN2, OUTPUT);
151
152
153
     154
155
156
    \vee BLYNK_WRITE ( V1 ) {
157
     set_point_ROW = param.asInt();
158
159
160 \vee BLYNK_WRITE ( V2 ) {
     set_point_PITCH = param.asInt();
164 VBLYNK_WRITE ( V3 ) {
    set_point_YAW = param.asInt();
     }
166
167
168
     void loop() {
       Blynk.run();
169
170
       if (mpu.dmpGetCurrentFIFOPacket(fifoBuffer)) {
         mpu.dmpGetQuaternion(&q, fifoBuffer);
         mpu.dmpGetGravity(&gravity, &q);
         mpu.dmpGetYawPitchRoll(ypr, &q, &gravity);
173
         Serial.print("Row = ");
174
         Serial.print(ypr[2] * 180 / M_PI);
Serial.print(" | Pitch = ");
175
176
         Serial.print(ypr[1] * 180 / M_PI);
177
178
         Serial.print(" | Yaw = ");
179
         Serial.print(ypr[0] * 180 / M_PI);
180
         ROW = ypr[2] * 180 / M_PI;
181
         PITCH = ypr[1] * 180 / M PI;
182
         YAW = ypr[0] * 180 / M_PI;
183
184
      185
186
187
188
       Present_time = micros();
189
       Delta_time = (float)(Present_time - Previous_time);
190
191
       Present_error_ROW = set_point_ROW - ROW;
192
       Intergral_error_ROW += Present_error_ROW * Delta_time;
193
       Devirative_error_ROW = (Present_error_ROW - Previous_error_ROW)/Delta_time ;
194
195
       if (Intergral_error_ROW >= Max_out ) Intergral_error_ROW = Max_out;
196
       else if(Intergral_error_ROW <= Min_out ) Intergral_error_ROW = Min_out;</pre>
197
       out_ROW = (kp*Present_error_ROW) + (ki*Intergral_error_ROW) + (kd*Devirative_error_ROW) ;
       if (out_ROW >= Max_out ) out_ROW = Max_out;
```

```
else if (out ROW <= Min out ) out ROW = Min out:
199
200
       Previous_error_ROW = Present_error_ROW;
201
202
      //PITCH PID
       Present_error_PITCH = set_point_PITCH - PITCH;
203
204
        Intergral_error_PITCH += Present_error_PITCH * Delta_time;
205
       Devirative_error_PITCH = (Present_error_PITCH - Previous_error_PITCH)/Delta_time ;
206
       if (Intergral_error_PITCH >= Max_out ) Intergral_error_PITCH = Max_out;
207
       else if(Intergral_error_PITCH <= Min_out ) Intergral_error_PITCH = Min_out;</pre>
       out_PITCH = (kp*Present_error_PITCH) + (ki*Intergral_error_PITCH) + (kd*Devirative_error_PITCH) ;
if (out_PITCH >= Max_out ) out_PITCH = Max_out;
208
209
       else if (out_PITCH <= Min_out ) out_PITCH = Min_out;</pre>
210
       Previous_error_PITCH = Present_error_PITCH;
211
212
213
214
       Present error YAW = set point YAW - YAW;
215
       Intergral_error_YAW += Present_error_YAW * Delta_time;
       Devirative_error_YAW = (Present_error_YAW - Previous_error_YAW)/Delta_time ;
       if (Intergral_error_YAW >= Max_out ) Intergral_error_YAW = Max_out;
217
218
       else if(Intergral_error_YAW <= Min_out ) Intergral_error_YAW = Min_out;</pre>
219
       out_YAW = (kp*Present_error_YAW) + (ki*Intergral_error_YAW) + (kd*Devirative_error_YAW);
       if (out_YAW >= Max_out ) out_YAW = Max_out;
220
       else if (out_YAW <= Min_out ) out_YAW = Min_out;</pre>
221
222
       Previous_error_YAW = Present_error_YAW;
223
       Previous time = Present time:
224
225
      //OUTPUT = out Print to check if it is in normal condition or not
226
       Serial.print(" ||| OUT_Row = ");
227
       Serial.print(out_ROW);
228
229
       Serial.print(" ||| OUT_Pitch = ");
230
       Serial.print(out_PITCH);
231
       Serial.print(" ||| OUT_Yaw = ");
       Serial.println(out_YAW);
232
233
234
235
      236
237
238
       dataArray[0] = out_ROW
239
       dataArray[1] = out_PITCH ;
       dataArray[2] = out_YAW
240
241
       Wire.beginTransmission(slaveAddress); //Address is queued for checking if the slave is present
242
243
         Wire.write(dataArray,3); //Data bytes are queued in local buffer
244
245
       Wire.endTransmission(); //All the above queued bytes are sent to slave on ACK handshaking
246
      247
248
      249
250
251
         if (out_ROW > 0 ) {
253
         // Move the motor forward
           digitalWrite(MOTORA_IN1, HIGH);
254
255
           digitalWrite(MOTORA_IN2, LOW);
           analogWrite(MOTORA_EN, abs(out_ROW));
256
257
258
         if (out_ROW < 0 ) {
259
         // Stop the motor
           digitalWrite(MOTORA_IN1, LOW);
260
           digitalWrite(MOTORA_IN2, HIGH);
261
           analogWrite(MOTORA_EN, abs(out_ROW));
262
263
264
         if (out ROW = 0 ) {
```

```
265
            // Stop the motor
266
            digitalWrite(MOTORA_IN1, LOW);
            digitalWrite(MOTORA_IN2, LOW);
267
            analogWrite(MOTORA_EN, 0);
268
269
270
      //FOR PITCH AXIS
271
272
          if (out_PITCH > 0 ) {
273
            // Move the motor forward
274
            digitalWrite(MOTORB_IN1, HIGH);
            digitalWrite(MOTORB_IN2, LOW);
275
            analogWrite(MOTORB_EN, abs(out_PITCH));
276
277
278
          if (out_PITCH < 0 ) {
279
            // Stop the motor
280
            digitalWrite(MOTORB_IN1, LOW);
281
            digitalWrite(MOTORB_IN2, HIGH);
            analogWrite(MOTORB_EN, abs(out_PITCH));
282
283
          if (out_PITCH = 0 ) {
284
285
            // Stop the motor
            digitalWrite(MOTORB_IN1, LOW);
digitalWrite(MOTORB_IN2, LOW);
286
287
            analogWrite(MOTORB_EN, 0);
288
289
290
      //FOR YAW AXIS
291
          if (out_YAW > 0 ) {
292
293
            // Move the motor forward
            digitalWrite(MOTORC_IN1, HIGH);
294
            digitalWrite(MOTORC_IN2, LOW);
295
            analogWrite(MOTORC_EN, abs(out_YAW));
296
297
298
          if (out_YAW < 0 ) {
            // Stop the motor
299
            digitalWrite(MOTORC_IN1, LOW);
300
301
            digitalWrite(MOTORC_IN2, HIGH);
            analogWrite(MOTORC_EN, abs(out_YAW));
302
303
304
          if (out_YAW = 0 ) {
305
            // Stop the motor
            digitalWrite(MOTORC_IN1, LOW);
306
            digitalWrite(MOTORC_IN2, LOW);
307
308
            analogWrite(MOTORC_EN, 0);
309
310
311
312
```

*หมายเหตุ โค้ดทั้งหมดสามารถดาวน์โหลด หรือดูได้จากลิงก์ตามนี้

https://github.com/Gaplnwzaza/MCE242-Project-Stabilizer

```
This MCE242 project was created by 65070502202 Kantapong Premyodin and 65070502204 Chutipon Likitparinya
        The project name is 3-Axis stabilizer with adjust value and PID
        NOTE: First we use esp32 to drive motor but esp32 cannot hold that much voltage so we have to use another board
4
        and that board is Arduino UNO R3 by I2C communication */
6
    DEETNE FOR T2C COMMUNICATION
8
    9
    #define slaveAddress 0x08 //you have to assign an 8-bit address to Slave
    int8_t dataArray[3] = { 0 , 0 , 0 };
11
    long raw_ROW, raw_PITCH, raw_YAW;
12
13
14
    17
    long map_ROW, map_PITCH, map_YAW;
18
    int state = 0:
19
    int gap_Degree = 15 ;
    int RmotorPin1 = 2;
    int RmotorPin2 = 3;
22
    int RmotorPin3 = 4;
23
24
    int RmotorPin4 = 5;
    int PmotorPin1 = 6;
    int PmotorPin2 = 7;
    int PmotorPin3 = 8;
    int PmotorPin4 = 9;
28
    int YmotorPin1 = 10:
29
30
    int YmotorPin2 = 11;
    int YmotorPin3 = 12;
    int YmotorPin4 = 13;
33
34
    void setup() {
     Wire.begin(slaveAddress);
35
      Serial.begin(115200);
36
37
     Wire.onReceive(receiveEvent); //You need to declre it in setup() to receive data from Master
38
39
      pinMode(RmotorPin1, OUTPUT);
40
     pinMode(RmotorPin2, OUTPUT);
     pinMode(RmotorPin3, OUTPUT);
42
     pinMode(RmotorPin4, OUTPUT);
43
     pinMode(PmotorPin1, OUTPUT);
     pinMode(PmotorPin2, OUTPUT);
44
     pinMode(PmotorPin3, OUTPUT);
45
46
     pinMode(PmotorPin4, OUTPUT);
47
      pinMode(YmotorPin1, OUTPUT);
48
      pinMode(YmotorPin2, OUTPUT);
49
      pinMode(YmotorPin3, OUTPUT);
50
      pinMode(YmotorPin4, OUTPUT);
51
    void loop() {
53
54
     raw ROW = dataArray[0];
     raw_PITCH = dataArray[1];
55
56
      raw_YAW = dataArray[2];
57
58
      Serial.print(" || RPY = ");
59
      Serial.print(dataArray[0], DEC);
60
      Serial.print(" || ");
      Serial.print(dataArray[1], DEC);
      Serial.print(" || ");
62
     Serial.print(dataArray[2], DEC);
63
64
65
     if (raw_ROW > gap_Degree) {
     map_ROW = map(raw_ROW, 0, 127, 8, 2);
```


```
67
        if (raw_ROW < -gap_Degree) {
    map_ROW = map(raw_ROW, -128, 0, -2, -8);</pre>
68
69
 70
         if (raw_ROW <= gap_Degree && raw_ROW >= -gap_Degree) {
 71
         map_ROW = 0;
 72
 73
 74
        if (raw_PITCH > gap_Degree) {
 75
          map_PITCH = map(raw_PITCH, 0, 127, 8, 2);
 76
 77
        if (raw_PITCH < -gap_Degree) {
   map_PITCH = map(raw_PITCH, -128, 0, -2, -8);</pre>
 78
 79
80
         if (raw_PITCH <= gap_Degree && raw_PITCH >= -gap_Degree) {
81
         map_PITCH = 0;
82
83
84
         if (raw_YAW > gap_Degree) {
85
86
          map_YAW = map(raw_YAW, 0, 127, 8, 2);
87
        if (raw_YAW < -gap_Degree) {</pre>
88
         map_YAW = map(raw_YAW, -128, 0, -2, -8);
89
 90
         if (raw_YAW <= gap_Degree && raw_YAW >= -gap_Degree) {
91
         map_YAW = 0;
92
93
94
         Serial.print(" -- mapRPY = ");
95
         Serial.print(map ROW);
 96
         Serial.print(" || ");
 97
        Serial.print(map_PITCH);
98
        Serial.print(" || ");
 99
100
        Serial.print(map_YAW);
         //For ROW axis
         if (state == 0) {
103
104
          //+ ROW axis
          if (map_ROW > 0) {
    Serial.println(" || +ROW");
105
106
107
             digitalWrite(RmotorPin1, HIGH);
108
             digitalWrite(RmotorPin2, LOW);
109
             digitalWrite(RmotorPin3, LOW);
110
             digitalWrite(RmotorPin4, LOW);
111
             delay(abs(map_ROW));
112
             digitalWrite(RmotorPin1, LOW);
113
             digitalWrite(RmotorPin2, HIGH);
114
             digitalWrite(RmotorPin3, LOW);
115
             digitalWrite(RmotorPin4, LOW);
116
             delay(abs(map_ROW));
117
             digitalWrite(RmotorPin1, LOW);
118
             digitalWrite(RmotorPin2, LOW);
119
             digitalWrite(RmotorPin3, HIGH);
120
             digitalWrite(RmotorPin4, LOW);
121
             delay(abs(map_ROW));
122
             digitalWrite(RmotorPin1, LOW);
123
             digitalWrite(RmotorPin2, LOW);
124
             digitalWrite(RmotorPin3, LOW);
125
             digitalWrite(RmotorPin4, HIGH);
126
            delay(abs(map_ROW));
127
           //- ROW axis
128
          if (map_ROW < 0) {
    Serial.println(" ||| -ROW");</pre>
129
130
             digitalWrite(RmotorPin1, LOW);
131
            digitalWrite(RmotorPin2, LOW);
132
```

```
133
            digitalWrite(RmotorPin3, LOW);
134
            digitalWrite(RmotorPin4, HIGH);
135
            delay(abs(map_ROW));
            digitalWrite(RmotorPin1, LOW);
136
137
            digitalWrite(RmotorPin2, LOW);
138
            digitalWrite(RmotorPin3, HIGH);
139
            digitalWrite(RmotorPin4, LOW);
140
            delay(abs(map ROW));
141
            digitalWrite(RmotorPin1, LOW);
            digitalWrite(RmotorPin2, HIGH);
142
143
            digitalWrite(RmotorPin3, LOW);
144
            digitalWrite(RmotorPin4, LOW);
145
            delay(abs(map_ROW));
            digitalWrite(RmotorPin1, HIGH);
146
147
            digitalWrite(RmotorPin2, LOW);
148
            digitalWrite(RmotorPin3, LOW);
149
            digitalWrite(RmotorPin4, LOW);
150
            delay(abs(map_ROW));
151
          if (map_ROW == 0) {
152
153
            state = 1;
154
155
156
      //state = 1
        //For PITCH axis
157
        if (state == 1) {
158
          //+ PITCH axis
159
          if (map_PITCH > 0) {
160
            Serial.println(" ||| +PITCH");
161
            digitalWrite(PmotorPin1, HIGH);
162
            digitalWrite(PmotorPin2, LOW);
163
            digitalWrite(PmotorPin3, LOW);
164
165
            digitalWrite(PmotorPin4, LOW);
166
            delay(abs(map_PITCH));
            digitalWrite(PmotorPin1, LOW);
167
168
            digitalWrite(PmotorPin2, HIGH);
169
            digitalWrite(PmotorPin3, LOW);
            digitalWrite(PmotorPin4, LOW);
170
171
            delay(abs(map_PITCH));
            digitalWrite(PmotorPin1, LOW);
172
173
            digitalWrite(PmotorPin2, LOW);
174
            digitalWrite(PmotorPin3, HIGH);
175
            digitalWrite(PmotorPin4, LOW);
176
            delay(abs(map_PITCH));
            digitalWrite(PmotorPin1, LOW);
177
178
            digitalWrite(PmotorPin2, LOW);
            digitalWrite(PmotorPin3, LOW);
179
180
            digitalWrite(PmotorPin4, HIGH);
181
            delay(abs(map_PITCH));
182
          //- PITCH axis
183
          if (map_PITCH < 0) {</pre>
184
185
            Serial.println(" ||| -PITCH");
            digitalWrite(PmotorPin1, LOW);
186
187
            digitalWrite(PmotorPin2, LOW);
            digitalWrite(PmotorPin3, LOW);
188
189
            digitalWrite(PmotorPin4, HIGH);
190
            delay(abs(map_PITCH));
191
            digitalWrite(PmotorPin1, LOW);
192
            digitalWrite(PmotorPin2, LOW);
            digitalWrite(PmotorPin3, HIGH);
193
194
            digitalWrite(PmotorPin4, LOW);
            delay(abs(map_PITCH));
195
196
            digitalWrite(PmotorPin1, LOW);
197
            digitalWrite(PmotorPin2, HIGH);
198
            digitalWrite(PmotorPin3, LOW);
```

```
199
            digitalWrite(PmotorPin4, LOW);
200
            delay(abs(map_PITCH));
            digitalWrite(PmotorPin1, HIGH);
201
            digitalWrite(PmotorPin2, LOW);
202
203
            digitalWrite(PmotorPin3, LOW);
            digitalWrite(PmotorPin4, LOW);
204
205
            delay(abs(map_PITCH));
206
207
          if (map_PITCH == 0) {
208
            state = 2;
209
210
211
      //state = 2
212
        //For YAW axis
        if (state == 2) {
213
          //+ YAW axis
214
215
          if (map_YAW > 0) {
216
            Serial.println(" ||| +YAW");
217
            digitalWrite(YmotorPin1, HIGH);
218
            digitalWrite(YmotorPin2, LOW);
            digitalWrite(YmotorPin3, LOW);
219
220
            digitalWrite(YmotorPin4, LOW);
221
            delay(abs(map YAW));
222
            digitalWrite(YmotorPin1, LOW);
223
            digitalWrite(YmotorPin2, HIGH);
224
            digitalWrite(YmotorPin3, LOW);
225
            digitalWrite(YmotorPin4, LOW);
226
            delay(abs(map_YAW));
227
            digitalWrite(YmotorPin1, LOW);
228
            digitalWrite(YmotorPin2, LOW);
229
            digitalWrite(YmotorPin3, HIGH);
230
            digitalWrite(YmotorPin4, LOW);
231
            delay(abs(map_YAW));
            digitalWrite(YmotorPin1, LOW);
232
233
            digitalWrite(YmotorPin2, LOW);
            digitalWrite(YmotorPin3, LOW);
234
235
            digitalWrite(YmotorPin4, HIGH);
236
            delay(abs(map_YAW));
237
238
          //- PITCH axis
239
          if (map_YAW < 0) {</pre>
            Serial.println(" ||| -YAW");
240
            digitalWrite(YmotorPin1, LOW);
241
242
            digitalWrite(YmotorPin2, LOW);
            digitalWrite(YmotorPin3, LOW);
243
244
            digitalWrite(YmotorPin4, HIGH);
245
            delay(abs(map_YAW));
246
            digitalWrite(YmotorPin1, LOW);
247
            digitalWrite(YmotorPin2, LOW);
248
            digitalWrite(YmotorPin3, HIGH);
249
            digitalWrite(YmotorPin4, LOW);
250
            delay(abs(map_YAW));
251
            digitalWrite(YmotorPin1, LOW);
            digitalWrite(YmotorPin2, HIGH);
252
253
            digitalWrite(YmotorPin3, LOW);
            digitalWrite(YmotorPin4, LOW);
254
255
            delay(abs(map_YAW));
256
            digitalWrite(YmotorPin1, HIGH);
257
            digitalWrite(YmotorPin2, LOW);
258
            digitalWrite(YmotorPin3, LOW);
259
            digitalWrite(YmotorPin4, LOW);
260
            delay(abs(map_YAW));
261
          if (map_YAW == 0) {
262
263
            state = 0;
264
```

```
265
      }
       //state = 3
266
        if (map_ROW != 0 && state != 0) {
267
        state = 0;
268
269
        if (map_PITCH != 0 && state == 2) {
270
271
        state = 1;
272
273
       //Stop State
        if (map_ROW == 0 && map_PITCH == 0 && map_YAW == 0){
274
        Serial.println(" ||| STOP");
275
276
277
        Serial.print("state = ");
278
        Serial.print(state);
279
280
      void receiveEvent(int howmany) //howmany = Wire.write()executed by Master ESP
281
282
        while (1 < Wire.available()) {
  for (int i = 0; i < howmany; i++) {</pre>
283
284
           dataArray[i] = Wire.read();
285
286
287
        }
      }
288
```

แผนผังการทำงานของอุปกรณ์ต่างๆ



สรุปผลการทดลอง

Stabilizer สำหรับผู้ป่วยรูมาตอยส์ยังไม่สามารถใช้งานได้จริงเนื่องจากการตอบสนองของ Stepper Motor ที่ใช้ในปัจจุบันนั้นมี Response Time ที่ช้าเกินไป แต่หากการเปลี่ยนองศาไม่ได้เกิดขึ้นอย่างเฉียบพลัน Stabilizer ยังคงสามารถทำงานได้อย่างปกติ

ปัญหาที่พบระหว่างการทดลอง

- 1. ESP32s ไม่สามารถใช้ในการควบคุมมอเตอร์ 28BYJ-48 ได้
- 2. ความเร็วการตอบสนองของมอเตอร์ไม่เป็นไปตามที่คิด

วิธีแก้ไข

- 1. ใช้ ESP32s ในการรับข้อมูลจาก MPU6050 และส่งข้อมูลให้ Arduino UNO เพื่อใช้ในการควบคุมมอเตอร์ 28BYJ-48
- 2. เปลี่ยนมอเตอร์และโค้ดให้มี Response Time ที่ดีขึ้น

ข้อเสนอแนะ

- 1. ขณะเริ่มทำงานไม่ควรขยับอุปกรณ์ เพื่อให้ MPU6050 (Gyroscope) ได้ทำการ Calibrate ตัวเองก่อน
- 2. หากโปรแกรมหยุดทำงาน สังเกตได้จากการที่ Stepper motor หมุนไม่หยุด ให้ทำการกดปุ่ม RESET แล้ว เริ่มการทำงานใหม่

วิดีโอสาธิตการทำงาน

https://youtu.be/N8c2kVaJQ_8

ไฟล์โครงงาน

https://github.com/Gaplnwzaza/MCE242-Project-Stabilizer