


Half frame Smith machine

Product ID. 7AK5J



Scan for Support



Distributed by
GARVEE.com

support@garvee.com

Read all precautions and instructions in this manual before using this equipment



Assembly Caution	3
Prart List	4-5
Hardware List	5
Step 1	6
Step 2	7
Step 3	8
Step 4	9
Step 5	10
Step 6	11
Step 7	12-13

ASSEMBLY

Make Things Easier for Yourself

Everything in this manual is designed to ensure that the weight system can be assembled successfully by anyone. However, it is important to realize that the versatile weight system has many parts and that the assembly process will take time. Most people find that by setting aside plenty of time, assembly will go smoothly.

Before beginning assembly, carefully read the following information and instructions:













- Assembly requires two people.
- Place all parts in a cleared area and remove the packing materials. Do not dispose of the packing materials until assembly is completed.
- Tighten all parts as you assemble them, unless instructed to do otherwise.
- As you assemble the weight system, make sure all parts are oriented as shown in the drawings.
- ***For help identifying small parts, refer to the PART IDENTIFICATION CHART on Pages 4 and 5.***

The following tools (not included) are required for assembly:





- Two adjustable wrenches 
- One rubber mallet 
- One standard screwdriver 
- One Phillips screwdriver 
- Lubricant, such as grease or petroleum jelly, and soapy water.

Assembly will be more convenient if you have a socket set, a set of open-end or closed-end wrenches, or a set of ratchet wrenches.





PART LIST

1  x 2	2  x 2	3  x 1	4  x 1
5  x 1	6  x 1	7  x 1	8  x 1
9  x 1	10  x 1	11  x 2	12  x 2
13  x 2	14  x 1	15  x 2	16  x 1
17  x 2	18  x 2	19  x 4	20  x 1
21  x 1	22  x 1	23  x 1	24  x 1
25  x 1	26  x 1	27  x 2	28  x 2
29  x 2	30  x 4	31  x 2	32  x 2


PART LIST


33  x 4	34  x 6	35  x 5	36  x 2
37  x 2	38  x 6	39  x 1	40  x 1
41  x 4	42  x 2		

HARDWARE LIST


43 M12X30mm Bolt  x 2	44 M10X70mm Bolt  x 27	45 M10X65mm Bolt  x 4	46 M10X45mm Bolt  x 3
47 M10X25mm Bolt  x 5	48 M10X20mm Bolt  x 4	49 M8X60mm Bolt  x 4	50 M8X10mm Bolt  Pre-installed x 4
51 M10 Washer  x 80	52 M8 Washer  x 4	53 M10 Nut  x 37	54 M8 Nut  x 4


STEP: 1

44 M10X70mm Bolt  x 4	49 M8X60mm Bolt  x 4	51 M10 Washer  x 8	52 M8 Washer  x 4
53 M10 Nut  x 4	54 M8 Nut  x 4		





STEP: 2

44 M10X70mm Bolt  x 18	51 M10 Washer  x 36	53 M10 Nut  x18
---	--	--






STEP: 3

45 M10X65mm Bolt  x 2	47 M10X25mm Bolt  x 4	51 M10 Washer  x 10	53 M10 Nut  x 4
--	--	--	--



STEP: 4


44 M10X70mm Bolt  x 2	45 M10X65mm Bolt  x 2	48 M10X20mm Bolt  x 2	51 M10 Washer  x 10
53 M10 Nut  x 4			




STEP: 5

43

M12X30mm Bolt




x 2





STEP: 6

48 M10X20mm Bolt  x 2	50 M8X10mm Bolt  x 4	51 M10 Washer  x 2
--	---	---



STEP: 7

44 M10X70mm Bolt  x 3	46 M10X45mm Bolt  x 3	47 M10X25mm Bolt  x 1	51 M10 Washer  x 14
53 M10 Nut  x 7			



STEP: 7

