

CONCEPTUAL MASTER SITE PLAN

06-271
9/25/07

ST. MALACHY

CATHOLIC CHURCH

407 WEST "E" STREET,
TEHACHAPI, CA. 93561

DIOCESE OF FRESNO

Architect:

Bill Brown AIA Professional Corporation

801 S. Tejon St.

Colorado Springs, CO. 80903

Phone: (719) 473-8138 Fax: (719) 473-8157

e-mail: info@billbrowniaia.com

www.billbrowniaia.com

06-271
9/25/07

WEST "F" STREET

PROPERTY LINE


PROPERTY LINE (880.63')

WEST "E" STREET

SOUTH MILL STREET

NOTE: BUILT AFTER THE AERIAL PHOTO WAS TAKEN

Phone: (719) 473-8138 Fax: (719) 473-8157
www.billbrowniaia.com
e-mail: info@billbrowniaia.com



2

ST. MALACHY

06-271
9/25/07

407 WEST "E" STREET, TEHACHAPI, CA. 93561



① ST. MALACHY CHURCH



② MCMULLAN HALL



③ K of C STORAGE



④ CATHOLIC DAUGHTERS
STORAGE



⑤ YOUTH MINISTRY



⑥ OFFICES

PHOTOGRAPHS OF EXISTING BUILDINGS

BILL BROWN AIA PROFESSIONAL CORPORATION

801 South Tejon Street
Colorado Springs, Colorado 80903
Phone: (719) 473-8138 Fax: (719) 473-8157
www.billbrowniaia.com
e-mail: info@billbrowniaia.com

ST. MALACHY

06-271
9/25/07

407 WEST "E" STREET, TEHACHAPI, CA. 93561

ITEMS MENTIONED BY PARISHIONERS IN CONFIDENTIAL "LOVE LETTERS" ABOUT THE PARISH TO BILL BROWN AIA PC, PRIOR TO PARISH LISTENING SESSION ON AUGUST 8, 2007

1. ADORATION CHAPEL- WOULD LIKE TO HAVE BUILT, POSSIBLY BUILT IN RECTORY AREA.
2. AIR CONDITIONING/HEATING- SEVERAL SAID DO NOT NEED, OTHERS WOULD LIKE IF POSSIBLE.
3. ALTAR- DO NOT CHANGE, WOULD LIKE MORE SPACE, LEAVE RAILING WHERE IT IS.
4. BAPTISMAL FONT- SEVERAL MENTIONED POSSIBLY MOVE TO FRONT OF CHURCH, SEVERAL MENTIONED DO NOT MOVE.
5. BATHROOMS- ENLARGED ENTRANCE FROM FOYER, NOT CHURCH, HANDICAP ACCESSIBLE, BABY CHANGING AREA, UPDATED.
6. BLESSED SACRAMENT CHAPEL- DO NOT WANT.
7. BRIDES ROOM- BACK OF CHURCH, ENTRANCE FROM FOYER.
8. CHOIR- LOFT, BACK OF CHURCH, TO INCLUDE SPACE FOR PIANO/ORGAN, INCLUDE STORAGE FOR EQUIPMENT. OTHERS MENTIONED, DO NOT NEED.
9. CHURCH- MAINTAIN SIMPLE BEAUTY OF ORIGINAL NATURAL WOOD. PROMOTE FEELINGS OF SERENITY AND PEACE, DO NOT DISTRACT WITH NEW RENOVATIONS, DO NOT LEVEL BUILDING, OVERALL HANDICAP ACCESSIBILITY, FIX, DO NOT CHANGE, ELEGANT AND SIMPLE.
10. "CRY-ROOM"- ADDED TO SANCTUARY, BACK OF CHURCH, POSSIBLY WEST WING OR NORTH WEST SECTION OF CHURCH. ABILITY TO SEE AND HEAR DURING MASS.
11. DOORS- REFURBISH, ADD WEATHER STRIPPING, POSSIBLY REPLACE.
12. FENCING- DECORATIVE, EFFECTIVE, SURROUNDING PERIMETER.
13. FLOORING- TILE OR CARPET, NOT RED, POSSIBLY DARK "WINE" COLOR EASIER TO KEEP CLEAN, NEW CARPET, NEW BASE BOARDS TO MATCH CARPET OR TILE, REPAIR UNDER PEWS.
14. FOOD PANTRY- ADDED ON GROUNDS.
15. FOYER- FRONT OF CHURCH, ABILITY TO COME IN FROM WEATHER, USED AS BOTH MEETING PLACE BEFORE CHURCH AND CRY AREA DURING CHURCH, ADDED CHOIR LOFT ABOVE IT, INCLUDE ENTRANCE TO BATHROOMS, NOT TOO LARGE, ADD BULLETIN BOARDS INSTEAD OF USING TAPE ON DOORS.
16. KNEELERS- KEEP AND REFURBISH, ADD CUSHIONS.
17. LABYRINTH- PLACE TO PRAY AND/OR MEDITATE WHILE WALKING A MAZE, INSIDE OR OUTSIDE.
18. LECTERN- NEW
19. LIBRARY- ADDED TO GROUNDS
20. LIGHTING- NEW, BRIGHTER FOR BETTER VISIBILITY, ABOVE OUR LADY OF GUADALUPE AND SACRED HEART.
21. MARIAN CHAPEL- SMALL (WEDDINGS, PRAYING)
22. McMULLAN HALL- EXPANSION, RENOVATION, ADD SOUTH FACING.
23. OLD SCHOOL BUILDING- DOES NOT NEED TO BE RENOVATED, RAZED.
24. OTHER- COMMUNITY INVOLVEMENT, HELP POOR, LISTEN TO YOUNG PEOPLE, USE MONEY TO HELP POOR, USE LOCAL CONTRACTORS, KEEP ARCHITECTURAL PERSONALITY, YOUTH FRIENDLY.
25. PEWS- REFURBISH, FIX BROKEN BOOK HOLDERS ON BACKS, WHEELCHAIR ACCESSIBLE, ADD MORE.
26. RECTORY- UPDATE AND REMODEL, POSSIBLE EXPANSION-OFFICES, MEETINGS.
27. ROUTING- IMPROVED AT ALTAR.
28. SACRISTY- RELOCATE
29. SANCTUARY- ENLARGED
30. SIDE CHAPEL- ADD.
31. SOUND SYSTEM- UPDATED SPEAKERS, MICROPHONES, ETC.
32. STATUES- DO NOT MOVE
33. TABERNACLE- DO NOT MOVE
34. WINDOWS- STAINED GLASS PRESERVED AND PROTECTED, DO NOT REPLACE UNLESS ABSOLUTELY NECESSARY.
35. YOUTH CENTER- ENLARGED AND UPDATED.

BILL BROWN AIA PROFESSIONAL CORPORATION

801 South Tejon Street
Colorado Springs, Colorado 80903
Phone: (719) 473-8138 Fax: (719) 473-8157
www.billbrownia.com
e-mail: info@billbrownia.com

407 WEST "E" STREET, TEHACHAPI, CA. 93561

ITEMS MENTIONED BY PARISHIONERS IN CONFIDENTIAL "LOVE LETTERS" ABOUT THE PARISH
TO BILL BROWN AIA PC, PRIOR TO PARISH LISTENING SESSION ON AUGUST 8, 2007

1. ADORATION CHAPEL- WOULD LIKE TO HAVE BUILT, POSSIBLY BUILT IN RECTORY AREA.
2. AIR CONDITIONING/HEATING- SEVERAL SAID DO NOT NEED, OTHERS WOULD LIKE IF POSSIBLE.
3. ALTAR- DO NOT CHANGE, WOULD LIKE MORE SPACE, LEAVE RAILING WHERE IT IS.
4. BAPTISMAL FONT- SEVERAL MENTIONED POSSIBLY MOVE TO FRONT OF CHURCH, SEVERAL MENTIONED DO NOT MOVE.
5. BATHROOMS- ENLARGED ENTRANCE FROM FOYER, NOT CHURCH, HANDICAP ACCESSIBLE, BABY CHANGING AREA, UPDATED.
6. BLESSED SACRAMENT CHAPEL-DO NOT WANT.
7. BRIDES ROOM- BACK OF CHURCH, ENTRANCE FROM FOYER.
8. CHORIR- LOFT, BACK OF CHURCH, TO INCLUDE SPACE FOR PIANO/ORGAN, INCLUDE STORAGE FOR EQUIPMENT. OTHERS MENTIONED, DO NOT NEED.
9. CHURCH- MAINTAIN SIMPLE BEAUTY OF ORIGINAL NATURAL WOOD, PROMOTE FEELINGS OF SERENITY AND PEACE, DO NOT DISTRACT WITH NEW RENOVATIONS, DO NOT LEVEL BUILDING, OVERALL HANDICAP ACCESSIBILITY, FIX, DO NOT CHANGE, ELEGANT AND SIMPLE.

BILL BROWN AIA PROFESSIONAL CORPORATION

801 South Tejon Street
Colorado Springs, Colorado 80903
Phone: (719) 473-8138 Fax: (719) 473-8157
www.billbrowniaia.com
e-mail: info@billbrowniaia.com

407 WEST "E" STREET, TEHACHAPI, CA. 93561

ITEMS MENTIONED BY PARISHIONERS IN CONFIDENTIAL "LOVE LETTERS" ABOUT THE PARISH
TO BILL BROWN AIA PC, PRIOR TO PARISH LISTENING SESSION ON AUGUST 8, 2007

10. "CRY-ROOM"- ADDED TO SANCTUARY, BACK OF CHURCH, POSSIBLY WEST WING OR NORTH WEST SECTION OF CHURCH, ABILITY TO SEE AND HEAR DURING MASS.
11. DOORS- REFURBISH, ADD WEATHER STRIPPING, POSSIBLY REPLACE.
12. FENCING- DECORATIVE, EFFECTIVE, SURROUNDING PERIMETER.
13. FLOORING- TILE OR CARPET, NOT RED, POSSIBLY DARK "WINE" COLOR EASIER TO KEEP CLEAN, NEW CARPET, NEW BASE BOARDS TO MATCH CARPET OR TILE, REPAIR UNDER PEWS.
14. FOOD PANTRY- ADDED ON GROUNDS.
15. FOYER- FRONT OF CHURCH, ABILITY TO COME IN FROM WEATHER, USED AS BOTH MEETING PLACE BEFORE CHURCH AND CRY AREA DURING CHURCH, ADDED CHOIR LOFT ABOVE IT, INCLUDE ENTRANCE TO BATHROOMS, NOT TOO LARGE, ADD BULLETIN BOARDS INSTEAD OF USING TAPE ON DOORS.
16. KNEELERS- KEEP AND REFURBISH, ADD CUSHIONS.
17. LABYRINTH- PLACE TO PRAY AND/OR MEDITATE WHILE WALKING A MAZE, INSIDE OR OUTSIDE.
18. LECTERN- NEW

BILL BROWN AIA PROFESSIONAL CORPORATION

801 South Tejon Street
Colorado Springs, Colorado 80903
Phone: (719) 473-8138 Fax: (719) 473-8157
www.billbrowniaa.com
e-mail: info@billbrowniaa.com

407 WEST "E" STREET, TEHACHAPI, CA. 93561

ITEMS MENTIONED BY PARISHIONERS IN CONFIDENTIAL "LOVE LETTERS" ABOUT THE PARISH
TO BILL BROWN AIA PC, PRIOR TO PARISH LISTENING SESSION ON AUGUST 8, 2007

19. LIBRARY- ADDED TO GROUNDS
20. LIGHTING- NEW, BRIGHTER FOR BETTER VISIBILITY, ABOVE OUR LADY OF GUADALUPE AND SACRED HEART.
21. MARIAN CHAPEL- SMALL (WEDDINGS, PRAYING)
22. MCMULLAN HALL- EXPANSION, RENOVATION, ADD SOUTH FACING.
23. OLD SCHOOL BUILDING- DOES NOT NEED TO BE RENOVATED, RAZED.
24. OTHER- COMMUNITY INVOLVEMENT, HELP POOR, LISTEN TO YOUNG PEOPLE. USE MONEY TO HELP POOR, USE LOCAL CONTRACTORS, KEEP ARCHITECTURAL PERSONALITY, YOUTH FRIENDLY.
25. PEWS- REFURBISH, FIX BROKEN BOOK HOLDERS ON BACKS, WHEELCHAIR ACCESSIBLE, ADD MORE.
26. RECTORY- UPDATE AND REMODEL, POSSIBLE EXPANSION-OFFICES, MEETINGS.
27. ROUTING- IMPROVED AT ALTAR.
28. SACRISTY- RELOCATE
29. SANCTUARY- ENLARGED
30. SIDE CHAPEL- ADD.

BILL BROWN AIA PROFESSIONAL CORPORATION

801 South Tejon Street
Colorado Springs, Colorado 80903
Phone: (719) 473-8138 Fax: (719) 473-8157
www.billbrowniaia.com
e-mail: info@billbrowniaia.com

407 WEST "E" STREET, TEHACHAPI, CA. 93561

ITEMS MENTIONED BY PARISHIONERS IN CONFIDENTIAL "LOVE LETTERS" ABOUT THE PARISH
TO BILL BROWN AIA PC, PRIOR TO PARISH LISTENING SESSION ON AUGUST 8, 2007

- 32. STATUES- DO NOT MOVE
- 33. TABERNACLE- DO NOT MOVE
- 34. WINDOWS- STAINED GLASS PRESERVED AND PROTECTED, DO NOT REPLACE
UNLESS ABSOLUTELY NECESSARY.
- 35. YOUTH CENTER- ENLARGED AND UPDATED.

BILL BROWN AIA PROFESSIONAL CORPORATION

801 South Tejon Street
Colorado Springs, Colorado 80903
Phone: (719) 473-8138 Fax: (719) 473-8157
www.billbrownaiia.com
e-mail: info@billbrownaiia.com

407 WEST "E" STREET, TEHACHAPI, CA. 93561

ITEMS MENTIONED BY PARISHIONERS IN SMALL GROUP DISCUSSION REPORTS AT PARISH LISTENING SESSION ON AUGUST 8, 2007

Group #1	
Design	Inviting
"Crying-Room"	Not needed
A/C & Heating	
Adoration Chapel	
Altar	Visible separation
Bridal Room	
Building/Restoration	Continue efforts
Choir	Possible loft
Church	Handicap Accessibility
Church	Entrance on west side, covered porch at front entrance
Communion Rail	
Exterior	Sports accommodations, outreach parking, storage
Fencing	Around perimeter
Flooring	Carpet
Organ/Piano	Own location space
Repairs	Kneelers, Pews
Sanctuary	Enlarge
Stained Glass	Preservation, protective coating
Stairs	Carpet
Tabernacle	Preserve, don't move
Group #2	
Altar	Enlarge
Bathrooms	Improve
Choir	Need own space, loft
Communion Rail	Keep
Flooring	New carpet, repair electrical outlets
Foyer	Back of church
Kneelers	Keep
Pews	More, refurbished
Sanctuary	Stay the same
Side Chapel	Not needed (only if tabernacle is not moved)
Sound System	Updated, all matching
Stained Glass	Remain in front of church
Tabernacle	Keep in place
Group #3	
"Cry-Room"	Part of foyer
Bagel/Meal Port	moved to left of church
Bathrooms	Improved, doors moved into foyer, handicapable

Bridal Room	Back of church
Chapel	Small, to left of church
Chapel	Left side of church for choir
Pews	Refurbish
Storage area	Moved and opened into choir area
Tabernacle	Stay center, work design around that
Group #4	
Artifacts	Keep those which reflect Catholicism of parishioners, i.e. tabernacle, crucifix, communion rail, statues
Budget	Can it support renovations and updates of safety codes
Church	Leave as is, fix safety issues, code requirements, handicapable, do not change Cross design of Church, extend in areas that don't change design
Communion Rail	Retained
Crucifix	Front, center
Design	Keep architecture and decor
Fans	Like fan shape around Altar for young and aged
Financial	Recognize financial limitations, frugal spending
Kneelers	Refurbish, replace
Pews	Arrangement for those with seeing eye dogs, due to alterations
Renovation or New Church?	All codes updated and met correctly
Safety Requirements	Front, center
Tabernacle	Update, all matching
Tradition	Remain in front of church design
Group #5	
"Cry-Room"	Much needed
Adoration Chapel	Behind existing Altar and Tabernacle
Bathrooms	Enlarged, extended to bell tower, hot water

Chapel	Behind Tabernacle
Choir	Loft, directly upstairs under roof
Church	More seating, keep traditional structure of church so it is, expand front, rest foyer, lose "Boxy" things in sanctuary, additional seating, restore shape of church
Communion Rail	Retain, keep
Expansion	Grass parking for adoration, daily mass chapel
Flooring	New carpet/replace with (marble)
Kneelers	Refurbished, new pews
Pews	Pads for seating, refurbished
Prayer Garden	Use
Sanctuary	Enlarged
Sound System	Now, consider flooring and sound of church
Stained Glass	Protect, strengthen, repair
Statues/Crucifix	Keep in church
Tabernacle	Do not move, focal point
Tabernacle	Front and center
Group #6	
A/C Heating	Needed
Altar	More storage behind
Bathroom	Door handles, rails, handicapable, enlarged
Bridal Room	Needed
Chapel	Behind Altar
Church	Now paint, keep original style, formal bulletin boards in vestibule
Communion Rail	Keep
Doors	Weather stripping, inside/outside
Exterior	Grassy lawn, plaza, coverage over entrances, fix sidewalk, church walk ways, West side can be "bumped out" for extra room
Foyer	Also used as "Cry-room"
McMillan Hall	Sound

Pews	Cushions
Safety	Bring up to code
Side Chapel	"Cry-room"
Statues/Crucifix	Keep
Tabernacle	Don't move
Group #7	
Adoration Chapel	
Altar	Separation of Altar and Tabernacle
Bathrooms	Improved, discolored location
Choir	Need choir loft
Day Care	Rooms on site
Entrance	To church improved
Flooring	Carpet
Foyer	New
Kneelers	Repairs
New Church	
Pews	Repairs
Sanctuary	Repairs, maintenance, love current look
Statues	need Shrines
Tabernacle	Front, center
Windows	Preserve stained glass
Group #8	
"Cry-Room"	Include window and speakers
A/C Heating	Concern, not priority
Adoration Chapel	Off back of church
Bathroom	More stalls, changing table
Choir	No loft, but area on side, out of sight, not so distracting
Communion Rail	Symbolic, distinguishes sacred space
Foyer	Enlarged, include bulletin boards
Handicap	ramp, shorter pews for accessibility
Kneelers	Keep, repair
Pews	Repair as necessary
Group #9	
Art Decor	Knights of Columbus pictures put back up
Bathrooms	Important, enlarge
Chapel	Behind Altar

Church	Enlarge
Communion Rails	Keep
Doors	Weather stripping, repair
Flooring	Tile
Foyer	Covered
Kneelers	Repair, keep
Pews	Repair, keep
Tabernacle	Front, center
Group #10	
Chapel	Behind Tabernacle
Choir	Loft or own space
Church	Congestion at front and rear, historic preservation (main design)
Crucifix	Front, center
Foyer	Enclosed (modified "Cry-Room")
Handicap	Accessibility, seating, bathroom
Kneelers	Repair, cushions
Pews	Repair, cushions
Sound System	Upgrade
Tabernacle	Front, center
Group #11	
"Cry-Room"	Other side of Sacred Heart
Altar	Statue
A/C & Heating	Add
Adoration Chapel	North side of church
Altar	More room
Altar Rail	Like
Bathrooms	Handicapable, changing tables
Bridal Room	In foyer
Chapel	Connected to church
Choir	Loft without destroying stained glass windows
Church	More room for wheelchair, alarm system, push walk back for men's room
Church	Insulation between confessionals
Crucifix	Like
Doors	Replaced with more ornate wood
Exterior	More sidewalk
Food Pantry	

Handicap	Accessibility, ramp, bathrooms
Lighting	Additional on outside of church
Railing	Going up stairs
Sanctuary	Larger, more storage area
Sound System	Enhance, travel throughout church, foyer, etc.
Stained Glass	Protect or replace with more saints
Statues	Like
Storage Facility	
Tabernacle	Front, center

BILL BROWN AIA PROFESSIONAL CORPORATION

801 South Tejon Street

Colorado Springs, Colorado 80903

Phone: (719) 473-8138 Fax: (719) 473-8157

www.billbrowniaa.com

e-mail: info@billbrowniaa.com

ST. MALACHY

06-271
9/25/07

407 WEST "E" STREET, TEHACHAPI, CA. 93561

ITEMS MENTIONED BY PARISHIONERS ON WRITTEN COMMENT CARDS HANDED IN AFTER EACH OF THE MASSES ON THE WEEKEND OF SEPTEMBER 8-9, 2007, AFTER REVIEWING DRAFT DRAWINGS OF CONCEPTUAL SITE MASTER PLAN

Adoration Chapel	where is it?
Air Conditioning/Heating	much needed
Altar	Arrangement is fine
Art Design	More religious around church
Baptismal Font	Move to front of church
Bathroom	Handicapable Looks fine Not necessary
	Far back as possible
	Leave rising
	Attach railing to altar
	Upgrades
	Expand for handicapped
	More toilets
Blessed Sacrament	Don't Change
Brical Room	Much needed
Children's Sunday School	needs more seating
Choir	More Room
	Seating, East or West side of church
	Loft on South end, back of church
Church	Do nothing
	Additional seating
	Stay the same
	Back used for dressing rooms, storage, restrooms, etc.
	Seating, more comfortable
	Elegant and simple
	leave alone
	larger than shown on drawings
	may not need extreme expansions due to population growth/elderly
	Lighten inside, no more white brick on inside
	Keep Catholic feel
	More space could be added to North side
	Expansion okay
Communion Rail	Don't change
	Leave alone
Crosses	Do not remove
Crucifix	Remain in center
	Don't Change
Cry-Room	keep as main focus
	much needed
	Un-wanted
Design	Exterior looks nice on drawings
	hard to understand what is being explained
	Liked master plan
	Covered area over vehicles, much liked
	Looks fine
	Essentials-new carpet, bathroom, paint
	Interior more in depth
	Looks good
	Keep interior same as old design
	Master Plan looks good

	Option 5 looks good
	need more detail, interior changes
	Love the design
	Would like to be larger
	Doesn't look much like improvements, can more be done
	Give more information on church itself
	Add weatherstripping
	Please fix sidewalks
Doors	
Exterior	Landscape, more trees, shrubs for shade and tranquility
	Metal Roofing, more durable
	repair sidewalk in front of church
	More welcoming
Fencing	Not all the way around church
Field	(out by playground) grassy area or more parking
Flooring	New carpet
Foyer	Front of Church
Gym	Either incorporated into youth center or hall
Kneelers	Do not remove, refurbish
Library	new and accessible
McMullan Hall	Expansion for larger functions
	Entrance extensions look like they're going into parking
Nursery	Better acoustics
Offices	Would like
	Remodeled
	Added to where field is now, use old offices as storage and future residence of groups
	Don't need to be expanded
Other	Expansion looks close to church size
	Meeting rooms
	Volunteer labor
	Spending Costs
	Chapel in Valley
	Use space to serve poor
	Game room for kids
	Gift Store
	Covered area, might cause traffic congestion
	Renewable sources, Passive and Active Solar, Recycled materials for building, Environmentally green as possible
	Reach out to Latino Community, space for youth programs and community participants
	Keep simple
	Costs, keep down.
	additions to be made of strong materials
Parking	adequate
	Good
	Do not reduce near church
Parochial School	Added to church
Pews	More comfortable, new, quiet
Rectory	Available through office
	Priest residence on property

Sacristy	Leave alone
Side Chapel	would like
	No
	Possibly on West side
Sound System	Possibly Video Projection
	update
	T.V. monitors to see everything from back of church better
Stations	keep where they are
Statues	Don't Change
	Do not remove
Tabernacle	Leave alone
	Front and center
	Do not remove
	Would like improvements of back drop behind it
	keep as main focus
Vestibule	needed
	Would like
Vestibule	Enclosed
West Side of Church	Complete expansion, new entry
Windows	More stained glass, preserved and protected
Youth Center	Redecorated, place to call their own
	might not be needed, review funds

BILL BROWN AIA PROFESSIONAL CORPORATION

801 South Tejon Street

Colorado Springs, Colorado 80903

Phone: (719) 473-8138 Fax: (719) 473-8157

www.billbrowniaa.com

e-mail: info@billbrowniaa.com

6

ST. MALACHY

06-271
9/25/07

407 WEST "E" STREET, TEHACHAPI, CA. 93561



EXISTING COUNTS (+/-):	
CURBSIDE PARKING	85
ONSITE PARKING	169
PEW LENGTH	712'
CHURCH SEATING (@ 18")	474
CHURCH SEATING (@ 22")	368

CITY REQUIREMENTS / EXISTING PARKING	
1 CAR/3.5 LIN. PEW LENGTH @ 712'	203 CARS
ONSITE + CURBSIDE PARKINGS	254 CARS

SETBACKS:	
FRONT YARD-WEST "E" ST.	20'-0"
SIDE YARD SOUTH MILL ST.	15'-0"
SIDE YARD-ADJACENT PROPERTY	5'-0"
REAR YARD-WEST "F" ST.	20'-0"
* FRONT, REAR, AND SIDE YARDS TO BE VERIFIED	

ZONING:	
R-1-8	SINGLE FAMILY RESIDENCE

LOT SIZE (+/-):	
5 ACRES	


NOTE:
ALL BUILDING AND PARKING DIMENSIONS ARE APPROXIMATE, TAKEN FROM AERIAL PHOTO (05/01/2006)

NOTE:
ALL PROPERTY BOUNDARIES, SETBACKS, ZONING, ETC. TO BE VERIFIED WITH CITY OF TEHACHAPI.

EXISTING SITE PLAN BILL BROWN AIA PROFESSIONAL CORPORATION

801 South Tejon Street
Colorado Springs, Colorado 80903
Phone: (719) 473-8138 Fax: (719) 473-8157
www.billbrownia.com
e-mail: info@billbrownia.com

30' 60'
GRAPHIC SCALE
APPROXIMATE




7

ST. MALACHY

06-271
9/25/07

407 WEST "E" STREET, TEHACHAPI, CA. 93561



EXISTING & PROPOSED COUNTS (+/-):			E	P
CURBSIDE PARKING			85	
ONSITE PARKING			169	200
PEW LENGTH			712'	1252'
CHURCH SEATING (@ 18")			474	834
CHURCH SEATING (@ 22")			388	683

CITY REQUIREMENTS / PROPOSED PARKING			
1 CAR/3.5 LIN. PEWS' LENGTH			357 CARS
ONSITE + CURBSIDE PARKING			285 CARS

SETBACKS:			
FRONT YARD-WEST "E" ST.			20'-0"
SIDE YARD-SOUTH MILL ST.			15'-0"
SIDE YARD-ADJACENT PROPERTY			5'-0"
REAR YARD-WEST "F" ST.			20'-0"

* FRONT, REAR, AND SIDE YARDS TO BE VERIFIED

ZONING:		
R-1-8		SINGLE FAMILY RESIDENCE

LOT SIZE (+/-):		
5 ACRES		

NOTE:
ALL BUILDING AND PARKING DIMENSIONS ARE APPROXIMATE, TAKEN FROM AERIAL PHOTO (05/01/2006)

NOTE:
ALL PROPERTY BOUNDARIES, SETBACKS, ZONING, ETC. TO BE VERIFIED WITH CITY OF TEHACHAPI.

CONCEPTUAL MASTER SITE PLAN BILL BROWN AIA PROFESSIONAL CORPORATION

801 South Tejon Street


Colorado Springs, Colorado 80903

Phone: (719) 473-8138 Fax: (719) 473-8157

www.billbrowniaa.com

e-mail: info@billbrowniaa.com

30' 60'
GRAPHIC SCALE
APPROXIMATE



8