



FCC Test Report **Report No. : FR550502**

Appendix A. Test Photos

1. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973




FCC Test Report

Report No.: FR550502

For radiated emissions 30MHz~1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973



FCC Test Report

Report No. : FR550502

For radiated emissions above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973