

1. VESSEL INSPECTION DETAILS (COMBINED REPORT)

Vessel ID:	hull_folder_combined
Report Number:	NautiCAI-2026-04-28-001
Inspection Type:	Automated Underwater Hull Assessment (Multi-Image)
Total Images in This Report:	3
Report Status:	COMPLETED - Audit Trail Generated
Vision engine:	prasad_multimodel_nauticai

2.1 IMAGE 1 OF 3 - HULL CONDITION FINDINGS


Inspection Date (this image):	2026-04-28 04:43:58
Total Hull Coverage:	100.0%
Overall Condition:	High
Fouling Areas Identified:	3

FR-4 (Heavy Macrofouling - Critical!)

!! IMMEDIATE CLEANING REQUIRED !!

Required Action: URGENT: Immediate dry-dock cleaning required!

Inspection frame - Image 1 of 3 (annotated)



2.2 IMAGE 2 OF 3 - HULL CONDITION FINDINGS

Inspection Date (this image): 2026-04-28 04:44:00

Total Hull Coverage: 100.0%

Overall Condition: High


Fouling Areas Identified: 2

FR-4 (Heavy Macrofouling - Critical!)

!! IMMEDIATE CLEANING REQUIRED !!

Required Action: URGENT: Immediate dry-dock cleaning required!

Inspection frame - Image 2 of 3 (annotated)



2.3 IMAGE 3 OF 3 - HULL CONDITION FINDINGS

Inspection Date (this image): 2026-04-28 04:44:01

Total Hull Coverage: 56.8797%

Overall Condition: High


Fouling Areas Identified: 3

FR-4 (Heavy Macrofouling - Critical!)

!! IMMEDIATE CLEANING REQUIRED !!

Required Action: URGENT: Immediate dry-dock cleaning required!

Inspection frame - Image 3 of 3 (annotated)



3. COMPLIANCE DECLARATION

This report was issued in accordance with IMO Biofouling Guidelines Resolution MEPC.207(62). All findings are fully repeatable and auditable. This combined report covers 3 image(s).