


1. Make sure the tested meter's terminal was tightened.




2. Make sure the current output terminal was tightened.






3. Make sure the test bench voltage terminal was not short circuited. See in the picture, the yellow line was mistakenly connected to the green line.



Picture below the yellow line was mistakenly connect to the black line



4. The correct way of voltage terminal connection.

