

(a) moderate suction, χΠ′>t; 0
exact rate equation
PT, 320 steps
PT, 320 steps, stored control
explicit strain form
p − p0 (Pa)
compression −εzz (10−3)
(b) strong suction, Π′<t; 0
exact rate equation
PT, 320 steps
PT, 320 steps, stored control
explicit strain form
p − p0 (Pa)
compression −εzz (10−3)
(c) Step convergence
max error / pressure change
moderate, 2D
moderate, 3D
moderate, 2D control
strong, 2D
strong, 3D
strong, 2D control
slope −1
PT steps over the loading