DAQ Load Cell Sensor Instructions

1	Make sure SD card is inserted; DAQ will remove and replace when necessary	
2	Flip switch to "on"	
3	Wait for LED to turn on; this indicates recording has started	
4	Begin testing and recording data	
5	When completed, flip switch to "off"; LED should turn off	

