



chadding connections 8, 31, 44 should fail at ~ 60 m/s

whech to see redistribution courts correctly.

butten connections 75, 105 should Pail

at ~ 65 m/s drech to see redistribution works, correctly,